

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 937)

Set Fir post, 4½ ft. long, 4" sq., 24" in the ground, for cor. of secs. 2, 3, 10, & 11, marked T21S S2 on NE, R9W S11 on SE, S10 SW, S3 on NW faces with 5 notches on S and 2 notches on the E edges; from which

- A Fir, 10" dia., bears N.24°30'E., 21 lks., mkd: T21S R9W S2 BT.
- A Fir, 30" dia. bears S.41°E. 40 lks. mkd: T21S R9W S11 BT
- A Fir, 24" dia., bears S.40°30'W., 63 lks., mkd: T21S R9W S10 BT.
- A Fir, 26" dia. bears N.44°W., 42 lks. mkd: T21S R9W S3 BT

BLM dependent resurvey by Norman J. McDonald, Cadastral Surveyor, under Group #350 April 1963/ - (DCSO records, Vol. 32 Page(s) 13135)

The cor. of secs. 2, 3, 10, & 11, determined at the record bearing & dist. from the remaining orig. BTs:

- A Fir, 43" dia. bears S.41°E. 40 lks. with partially opened blaze.
- A down Fir, 30" dia., bears S.40½°W., 63 lks., with partially opened blaze.
- A Fir stub, 40" dia. bears N.44°W., 42 lks with scribe marks T21S R visible on split open face.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S	R9W
S 3	S 2
S 10	S 11
1963	

from which a new BT

- A Fir, 42" dia., bears S.72½°E., 19 lks., mkd: T21S R9W S11 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14237-8)

The cor. of secs. 2, 3, 10, & 11, monumented with an iron post, 2½" dia., extending 4" above ground, firmly set, with properly mkd brass cap.

from which the OBT:

- A fir, 43" dia., bears S.41°E., 40 lks., with no marks visible on partially opened blaze.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

The stump hole of a fallen fir, 30" dia., bears S.40½°W., 63 lks., with fragmentary scribe marks visible on partially opened blaze.
A fir stub, 40" dia., bears N.44°W., 42 lks. with scribe marks T21S R visible on partially opened blaze.
and a BT marked by McDonald in 1963
A Fir, 42" dia., bears S.72½°E., 19 lks., with scribe marks T21S R9W S11 BT visible on open blaze.
and a new BT
A Hemlock, 10" dia., bears S.67°W., 33 lks., mkd: T21S R9W S10 BT.
No suitable trees available within limits in secs. 2 & 3.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO rec Vol. 56 Pg 22344)

The cor. of secs. 2, 3, 10, & 11, remonumented by McDonald in 1963, and rehabilitated by Peterson in 1966-67; monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.
from which the remains of the original bearing trees
A roothole bears S.41°E., 26.4 ft., alongside of which is a down fir, 45" dia., with a healed blaze.
A decayed fir pile, size indeterminate, bears N.44°W., 27.7 ft., no marks visible.
and the remains of a bearing tree mkd. by McDonald
A very decayed shattered fir stump, size indeterminate, bears S.72½°E., 12.5 ft., alongside of which is a down decayed fir, size indeterminate, with remains of a healed blaze on detached remains.
and new bearing trees
A fir, 13" dia. bears N.9¼°E., 24.9 ft mkd. T21S R9W S2 BT
A fir, 20" dia bears S.60¼°E. 59.1 ft mkd. T21S R9W S11 BT
A fir, 13" dia., bears S.76°W., 42.3 ft mkd. T21S R9W S10 BT. Mag Nail on left side center.
A fir, 27" dia. bears N.6¾°W., 50.1 ft mkd. T21S R9W S3 BT

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23167)

The cor. of secs. 2, 3, 10, and 11, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with a brass cap mkd.
from which the remains of the original bearing trees
A root hole bears S.41°E., 26.4 ft., alongside of which is a down fir, 38" dia., no marks visible. cont. next pg

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, size indeterminate, bears N.44°W., 27.7 ft., no marks visible.
and the remains of a bearing tree mkd. by McDonald in 1963
A decayed fir stump, size indeterminate, bears S.72½°E., 12.5 ft., no marks visible.
and the bearing trees mkd. by Forkner in 2009-10
A fir, 14" dia., bears N.9¼°E., 24.9 ft., with no scribe marks visible on partially healed blaze and a mag nail at the base on right side center.
A fir, 21" dia., bears S.60¼°E., 59.1 ft., with scribe marks T21S R9W S11 BT visible on partially healed blaze and a mag nail at the base on right side center.
A fir, 15" dia., bears S.76°W., 42.3 ft., with scribe marks R9W S1 visible on partially healed blaze and a mag nail at the base on left side center.
A fir, 30" dia., bears N.6¾° W., 50.1 ft., with illegible scribe marks visible on partially healed blaze and a mag nail at the base on right side center.