

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 939)

Set Hemlock post, 4½ ft. long, 4" sq., 24" in the ground for ¼ sec. cor., mkd: ¼ S on W face; from which

A Hemlock, 6" dia. bears N.87°15'E., 30 lks., mkd: ¼ S BT.

A Fir, 50" dia., bears N.20°15'W., 91 lks., mkd: ¼ S BT.

BLM dependent resurvey by Norman J. McDonald, Cadastral Surveyor, under Group #350 April 1963/ - (DCSO records, Vol. 32 Page(s) 13136)

The ¼ sec. cor. of secs. 2 & 3 determined at the record bearing & distance from the orig. BTs:

A Hemlock, 18" dia. bears N.87¼°E., 30 lks., with the scribe mark S on partially healed blaze.

A Fir, 64" dia., bears N.20¼°W., 91 lks., with the scribe mark S on opened blaze.

At the corner point

Set an iron post, 30" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S R9W

¼

S 3 | S 2

1963

from which a new BT

A Hemlock, 14" dia. bears N.39½°W., 24 lks., mkd: ¼ S3 BT.

Fd. & used on BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14240)

Douglas Co. Surveyors Office - John M. Powell - J. Heritage - May 1971 - C.S. File 53/66-19

Found - BLM brass cap, dated 1963, properly marked, buried under large log.

18" Hemlock down N.39°W., 15.5 ft. scribed visible "4 S3".

22" Hemlock dead N.87°E., 19.8 ft. shows scar.

New BTs- 12" Maple S.79°E., 39.0 ft. scribed ¼ S2 CS BT.

9" Hemlock S.69°W., 31.5 ft. scribed ¼ S3 CS BT.

continued next page

1

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO rec Vol. 56 Pg 22344)

The ¼ sec. cor. of secs. 2 and 3, remonumented by McDonald in 1963, utilized by Peterson in 1966-67, and rehabilitated by the Douglas County Surveyor in 1971; monumented with an iron post, 2½" dia., firmly set, with top 2" below the surface of the ground, with a brass cap, oriented NE., (properly) mkd. from which the remains of an original bearing tree

A decayed fir stump, 64" dia., bears N.20¼°W., 60.1 ft., no marks visible.

and the remains of a BT mkd. by the Douglas County Surveyor

A decayed maple stump, size indeterminate, bears S.78¾°E. 38.7 ft., no marks visible.

and new bearing trees

A fir, 20" dia., bears S.74¼°E., 34.0 ft., mkd. ¼ S2 BT.

A fir, 12" dia., bears S.85½°W., 73.1 ft., mkd. ¼ S3 BT.

A steel fence post, broken off, found lying loose NE., 10 ft. Corner is located on the N. edge of a triangular shaped stand of alder, 150 ft. wide by 150 ft. long, bounded to the SE. by an abandoned graveled road, 10 ft. wide, extending N.55°E. and S.75°W., and to the SW. by a graveled road, 12 ft. wide, extending N.35°W. and S.10°E.