

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 24, & 25

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 919)

-----  
Set hemlock post 4½ ft. long 4" sq. 24" in the ground on steep hill sloping NW for Cor. to secs. 13, 14, 23, & 24 marked T 21 S S 13, on NE, R 9 W S 24 on SE, S 23 on the SW, and S 14 on the NW faces with 3 notches on the S and 1 notch on the E edges, from which

A Hemlock, 12" dia., bears N.48°E., 13 lks., mkd: T21S R9W S13 BT.

A Hemlock, 10" dia., bears S.71°E., 20 lks., mkd: T21S R9W S24 BT.

A Hemlock, 12" dia., bears S.68°W., 27 lks., mkd: T21S R9W S23 BT.

A Fir, 48" dia. bears N.55°W. 29 lks. mkd: T21S R9W S14 BT

-----  
Dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967. (DCSO rec Vol. 34 Pgs 14224-5)

-----  
From the cor. of secs. 13, 14, 23, & 24, determined at rec. bearing & distance from the remains of the orig. BTs:

A stump hole, bears N.48°E., 13 lks.

The stump hole of a fallen & decayed hemlock, 12" dia., bears S.71°E., 20 lks. with no marks remaining.

The stump hole of a fallen & decayed hemlock, 12" dia., bears S.68°W., 27 lks. with no marks remaining.

A sawed fir stump, 60" dia., bears N.55°W., 29 lks., with axe marks visible on remaining bottom portion of old blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S R9W  
S 14 S 13  
S 23 S 24

1966

A Fir, 4" dia. bears N.80°E., 66 lks. mkd: T21S R9W S13 BT

A Fir, 4" dia. bears S.40½°E. 17 lks. mkd: T21S R9W S24 BT

An Alder, 9" dia., bears S.66°W., 39 lks., mkd: T21S R9W S23 BT.

A Fir, 4" dia., bears N.17½°W., 131 lks., mkd: T21S R9W S14 BT.

-----  
Fd. & used on Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, under Group #1735, surveyed June 1994/March 1995. (DCSO rec Vol. 52 Pgs 19692-3)

Fd. Ok 3/1996 Clyde Mulkins, M 123-67