

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 700304

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30 only, T21-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 888)

Set post 6" dia., 4 ft. long, with marked stone 12" in ground for cor. to secs. 19, 30, 24 and 25, marked T21S S19 on NE.; R8W S30 on SE.; R9W S25 on SW.; and S24 on NW. faces, with 4 notches on N. and 2 on S. edges, from which
Cherry 8" dia., bears S.78°W., 60 lks. dist. mkd. T21S R9W S25 BT.
Cherry 8" dia., bears N.45°W., 14 lks. dist. mkd. T21S R9W S24 BT.
Cherry 10" dia., bears N.52°E., 30 lks. dist. mkd. T21S R8W S19 BT.
Cherry 12" dia., bears S.26°E., 8 lks. dist. mkd. T21S R8W S30 BT.

GL0 survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 916 and 917)

(Found corner as described)
I find also that there had been established a corner near where I intersected the E. bdy. of Tp. (T21-9) but had been destroyed.

GL0 Resurvey by Norman D. Price and George Rigby, Cadastral Engineers, under Group #282, Surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11382)

(After a careful investigation, it is developed that Gesner's recorded retracement of this line is entirely fictitious, that it is a deliberate fabrication on his part for the purpose of justifying his own work and creating a limiting boundary for T21S R9W., and is therefore rejected as a suitable basis for restoration of lost corners referring to T21S R8W.) (Vol. 27 Pg. 11379)

The Sec. cor., the locus of which is determined by reference to the record bearing and distance from the old NE. and SE. bearing trees.

At the corner point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 21 S	T 21 S
R 9 W	S 19
S 24	S 30
	R 8 W
	1945

(Cont. Next Page)

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 700304

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30 only, T21-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>from which The stump hole and badly decayed remains of a Cherry, bears N.52°E., 30 lks. dist., with no marks remaining on this old bearing tree. The stump hole and badly decayed remains of a Cherry, bears S.26°E., 8 lks. dist., with no marks remaining on this old bearing tree. A Fir 54" dia., bears N.17½°E., 360 lks. dist., mkd. T21S R8W S19 BT. (New BT) A dead Fir 52" dia., bears S.20°E., 135 lks. dist., mkd. T21S R8W S30 BT. (New BT)</p>
<p>Douglas Co. Surveyors Office - John M. Powell, and crew - May 11, 1973 - C.S. File 56/25-20 ----- Found - GLO brass cap, properly mkd. (1945) 52" Fir stump, burnt, S.20°E., 89.1 ft., shows part of face. 54" Fir stump, burnt, N.17½°E., 237.6 ft. New BTs- 5" D.Fir N.54°E., 7.3 ft. scribed S19 CS BT. 5" D.Fir S.59°E., 19.1 ft. scribed S30 CS BT. Cor. lies in old clear cut very brushy. Also lies on westerly slope.</p>
<p>Clyde Mulkins, L.S. #2006 - For: IP Timber Lands Operating Co. LTD - Oct. 1995 - M 123-22 ----- Found - 1945 GLO brass cap 52" D.Fir stump, badly burned, bears S.20°E., 135 lks. (1945) 54" D.Fir uprooted stump, bears N.17½°E., 360 lks., no visible marks. (1945) 13" D.Fir, bears N.54°E., 7.3', with a healed face, not tagged. 15" D.Fir, bears S.59°E., 19.1', with a healed face, not tagged. New BTs- 14" D.Fir, bears N.6°E., 26.3', scribed "T21S R8W S19 BT" 12" D.Fir, bears S.62°E., 4.8', scribed "T21S R8W S30 BT" 15" D.Fir, bears S.4°E., 16.7', scribed "T21S R8W S30 BT" 12" D.Fir, bears N.59°W., 21.0', scribed "T21S R9W X BT"</p>
<p>Monument bent, FD. 6 BTs - by Ron Rice - 2/19/2003 - C.S. File 65/45-7</p>