

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, under contract No. 116 dated Dec. 12, 1867 - (DCSO records Vol. 3 Page(s) 1003)

Set stone, 18x9x6 for ¼ sec. corner from which
A Fir, 24" dia., bears S.65°W., 7 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1146)

Intersect the old ¼ sec. cor., which is a stone, loosely set, marked & witnessed as described by the Surveyor General. Alongside the old stone set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ Sec. cor., with brass cap mkd:
$$\frac{1}{4} \begin{matrix} S & 6 \\ S & 7 \end{matrix}$$

1919
from which
A Fir, 34" dia., bears N.30°W., 17 lks., mkd: ¼ S6 BT.
A Fir, 40" dia., bears S.65°W., 7 lks., mkd: ¼ S7 BT. OBT

Herman A. Pieske, RLS #1651 - For: USFS - Nov. 1984 - M 97-77
A & B

Found - 1" IP, cap broken off lying alongside. GLO 1919
36" orig. Fir stump, badly rotted bears S.60°W., 4.2 ft., no face visible.
42" Fir stump badly rotten bears N.30°W., 11.1 ft., visible scribes "¼ S6"
Set - 2½" x 30" alum. pipe, 24" in the ground, with 3¼" alum. cap mkd: US Dep of Agri-Forest Service T21S R10W ¼ S6 S7 RLS 1651 1983 Unlawful to Disturb.
Buried GLO cap alongside.
16" Forked D.Fir bears N.36°W., 15.3 ft. (8" Fork to West) faced & scribed "¼ S6 BT"
28" D.Fir bears S.29°W., 17.5 ft. faced & scribed "¼ S7 BT"