

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1134-5)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor., with brass cap mkd:

1/4
S 19|S 20
1919

from which

A Hemlock, 14" dia., bears S.79°E., 43 lks., mkd: 1/4 S20 BT.

An Alder, 12" dia., bears N.36°W., 48 lks., mkd: 1/4 S19 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - May 1968 - C.S. File 54/1-9

Found - 1919 GLO brass cap, broken off, concrete filled IP under logs & road construction debris, & OBTs mkd in 1919 as follows:

14" now 26" Hemlock, alive, S.79°E., 28.4 ft., shows good scar, we do not open.

12" now 24" Alder, N.36°W., 31.7 ft., turned out, shows scar on lower side.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T21S R10W OFFICE 1968 1/4 S 19|S 20

9" Hemlock N.78°E., 25.2 ft., mkd: 1/4 S20 CS BT.

13" Maple S.76°W., 17.5 ft., mkd: 1/4 S 19 CS BT

Note - This corner lies on steep N. slope approx. 66 ft. N of USFS Rd. #2138. Deposit old corner material alongside brass cap.