

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1047)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for
¼ sec. cor. of sec. 32 only, with brass cap mkd: ¼ S 32
1919

from which

An Alder 10" dia., bears N.35°E., 16 lks. dist. mkd. ¼ S32
BT.

An Alder 8" dia., bears N.35°W., 6 lks. dist. mkd. ¼ S32
BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack
Heritage, V. Perron, crew - May 1968 - C.S. File 54/1-29

Found - I.P., filled with concrete with brass cap broken off
and found in duff when excavating for new
monument.

10" now 16" Alder, badly decayed, N.35°E., 13.9 ft.
(Rec. 10.6 ft.) We open and find edge of axe
blaze.

Only hole where NW BT probably stood, fits record
bearing and distance.

Set Brass cap at cor. mkd: County Surveyors Office
T21S R10W ¼ S 32
T22S 1968

Deposit old corner material alongside.

New BTs -12" D.Fir N.45°E., 26.0 ft. mkd. ¼ S32 CS BT.

7" D.Fir N.11°W., 13.9 ft. mkd. ¼ S32 CS BT.

This corner lies on steep NW. slope, 50 ft. W. of spur.