

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1015)

Set 1/4 Sec. post, from which  
A Fir, 15" dia., bears North 2 lks.  
A Fir, 24" dia., bears South 24 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1067 & 1123)

Pg. 1067  
Retracing the line bet. Secs. 16 & 21; at 40.00 chs find no trace of the 1/4 sec. cor., set temp. 1/4.  
Pg. 1123, 39.18 chs. (N.87°37'W.)  
Apportioned distance, point for 1/4 sec. corner in ravine, course NW, where it is impracticable to reestablish 1/4 sec. corner.  
39.68 chs (N.87°37'W.)  
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for witness cor. to the 1/4 Sec. cor., with brass cap mkd:

1/4 S 16  
S 21 WC  
1919

from which  
An Alder, 12" dia., bears N.48°W., 38 lks., mkd: WC 1/4 S16 BT.  
A Cedar, 18" dia., bears S.41°E., 69 lks., mkd: WC 1/4 S21 BT.

Herman A. Pieske, RLS #1651 - For: USFS, Cooked Wassen Cadastral Survey - Aug. 1984 - M 97-33 A & B

Found - 1" iron pipe filled with concrete. No cap. Found charcoal in hole.  
20" Alder bears N.46°W., 25.1 ft (OBT, rec. N.48°W.)  
24" Cedar bears S.40°E., 45.5 ft (OBT rec. S.41°E.)  
Set - 2 1/2"x30" alum. pipe, 22" in the ground w/3 1/4" alum. cap mkd: "US Dep. of Agri-Forest Service  
33.0 ft. → T21S R10W WC 1/4 S16 S21 RLS 1651 1983  
UNLAWFUL TO DISTURB"