

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1109)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for
¼ Sec. cor., with brass cap mkd:

¼
S 33|S 34
1919

from which

A Fir, 14" dia., bears East, 2 lks., mkd: ¼ S34 BT.

A Fir, 14" dia., bears S.53°W., 21 lks., mkd: ¼ S33 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Feb. 1970 - C.S. File 54/1-21

Found - Remains of old concrete filled iron pipe with 1919
GLO brass cap laying alongside.
Orig. 14" now 16" Fir snag, East 1.3 ft., open &
find "¼ S34 BT" scribe & reverse.
Orig. 14" now 22" Fir, alive, S.53°W., 13.9 ft.,
shows good scar. Rescribe above old scar: "¼ S33
CS BT"

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T21S R10W
OFFICE, 1970 ¼ S 33|S 34

Deposit old cor. material alongside.

24" D.Fir N.65°E., 8.8 ft., mkd: ¼ S34 CS BT.

This corner lies on very steep, NE slope in very dense
rhododendron brush.