

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 404300

PRIMARY CORNER DESCRIPTION South Sec. Cor. Secs. 21 & 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1100)

75.50 chs.  
(A point south of the cor. of secs. 15, 16, 21 & 22)  
Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 21 & 22, with brass cap mkd:

T21S R10W  
S 21|S 22  
1919

from which  
A Fir, 10" dia., bears N.20°E., 16 lks., mkd: T21S R10W S22 BT.  
A Fir, 20" dia., bears N.29°W., 29 lks., mkd: T21S R10W S21 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1968 - C.S. File 54/1-19

Found - 1919 GLO brass cap properly marked & firmly set, pipe badly rusted.  
Orig. 10", now 12" Fir snag, N.30°E., (rec. N.20°E.) 10.6 ft., most of blaze rotted away, possible scribe visible.  
Orig. 20" now 28" Fir, alive, N.29°W., 19.1 ft., shows very good scar. We do not open. Rescribe "T21S R11W S21 CS BT"

Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S T21S R10W OFFICE 1968 S21|S22  
Deposit old corner materials alongside.

Note - 20" D.Fir N.57°E. 29.3 ft. mkd: T21S R10W S22 CS BT.  
This corner lies about 155 ft., E. of top of ridge, course NE-SW. Record dist. is 297 ft., E. of corner of secs. 27 & 28.