

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 500530

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 10 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1094-5)

(Midpoint on E bdy. of Sec. 10)
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor. of Sec. 10 only, with brass cap mkd:

1/4
S 10|
1919

from which
An Alder, 8" dia., bears S.60°W., 12 lks., mkd: 1/4 S10 BT.
A Fir, 36" dia., bears N.38°W., 24 lks., mkd: 1/4 S10 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/1-13

Found - 1" iron pipe filled with concrete, badly rusted & brass cap broken off.
Orig. 36" now 46" Fir, alive, N.38°W., 15.8 ft., alive, shows good scar.
SW BT gone, find hole where it would of been.
Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S T21S R10W OFFICE, 1968 1/4 S 10|
9" Cedar N.68°W., 13.1 ft., mkd: 1/4 S10 CS BT.
12" Hemlock N.6°W., 26.0 ft., mkd: 1/4 S10 CS BT.
Note - Deposit old pipe & brass cap alongside new monument.
This corner lies approx. 70 ft. S. of top of spur ridge, course W.

Fd. Ok by Eugene Bloom, 12/1983 - M 95-79