

PRIMARY CORNER DESCRIPTION West 1/4 Sec. 11 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1095)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor. S 11 only, with brass cap mkd:

1/4
|S 11
1919

from which

- An Alder, 10" dia., bears N.47°E., 74 lks., mkd: 1/4 S11 BT.
- A Hemlock, 36" dia., bears S.70°E., 48 lks., mkd: 1/4 S11 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/1-14

Found - 1" iron pipe filled with concrete at corner point, brass cap broken off & gone.
Orig. 36" now 46" Hemlock, alive, S.70°E., 31.7 ft., shows good scar. Rescribed: 1/4 S11 CS BT.
NE BT gone.
Call on creek to north & call dist. between 1/4 S10 & 1/4 S11 fits good.

Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S T21S R10W OFFICE, 1968 1/4|S 11

Note - 14" Hemlock N.89°E., 62.9 ft., mkd: 1/4 S11 CS BT.
Deposit old pipe alongside new monument.
This corner lies on very steep northerly slope 46 ft., S. of creek.

Herman A. Pieske, RLS #1651 - For: US Forest Service - Dec. 1983 - M 95-79 A & B

Found - 1" iron pipe with 2 1/2" brass cap, loose and sloping, properly marked.
Set - Reset pipe in orig. position & constructed large mound of stones.
16" Hemlock bears S.26°E., 19.4 ft., blazed & scribed "1/4 S11 BT.
6" Alder bears S.74°E., 48.3 ft., bark scribed "1/4 S11 BT"