

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer f. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1074)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for
1/4 Sec. cor., with brass cap mkd:

1/4
S 35|S 36
1919

from which

- A Fir, 16" dia., bears N.6°E., 10 lks., mkd: 1/4 S36 BT.
- A Fir, 24" dia., bears N.60°W., 12 lks., mkd: 1/4 S35 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1968 - C.S. File 54/1-15

Found - 1919 GLO brass cap, broken off from concrete filled pipe, still in place.

Orig. 16", now 24" Fir, alive, N.6°E., 6.6 ft., shows good scar.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T21S R10W
(Deposit old corner OFFICE 1968 1/4 S 35|S 36 material alongside)

New BTs- 18" D.Fir, N.34 1/2°W., 33.1 ft., mkd: "1/4 S35 CS BT"
15" D.Fir, S.27°E., 32.3 ft., mkd: "1/4 S36 CS BT"

Corner lies on steep SW slope 1 chain S. of small spur, SW.