

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 36 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1038)

Set an Iron post 3 ft. long, 1" dia., 26" in the ground for
¼ sec. cor. of sec. 36 only, with brass cap mkd: ¼ $\frac{S\ 36}{1919}$

from which,

A Fir 8" dia., bears N.24°E., 38 lks. dist. mkd. ¼ S36 BT.
A Fir 6" dia., bears N.65°W., 21 lks. dist. mkd. ¼ S36 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - June/July 1968- C.S. File 54/1-8

Found - 1919 GLO brass cap, laying on ground, pipe broken
off 10" below surface.

Orig. 8" now 9" Fir snag, N.24°E., 25.1 ft., "36"
scribe visible on open blaze, badly decayed.

Orig. 6" now 24" Fir, alive, N.55°W., (Rec. N.65°W.)
13.9 ft., shows fair scar. We do not open.

Rescribed "¼ S36 CS BT"

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S $\frac{1}{4}$ S 36

T 22 S R10W

1968

Deposit old cor. material alongside brass cap.

New BT - 28" D.Fir N.25°E., 45.3 ft. mkd. ¼ S36 CS BT.

This cor. lies on moderate southerly slope in timber and
brush, approx. 348 ft. S.88°W. of N¼ Sec. 1, T22-10W.

Tony Hostetter - For: Roseburg Resources - Jan. 2020 - C.S.
File 65/105-10

Found - 1968 DCSO brass cap from which:

1968 BTs described by Tracy are now stumps.

New BTs- 18" Fir, marked "X", BT tag, bears; N.8°25'E., 10.5
ft to spike.

10" Fir, marked "X", BT tag, bears; S.80°35'E., 16.4
ft to spike.

10" Fir, marked "X", BT tag, bears; S.03°14'E., 13.2
feet to spike.

14" Fir, marked "X", BT tag, bears; S.60°45'W., 10.8
feet to spike.