

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION Cl. Cor. T20 & 21S, R11W

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 118)

-----  
At point of intersection (295 lks. So. of cor. to Tps. 20 & 21 S., Rs. 11 & 12 W.) I set a post 4½ ft. long, 4" sq., 24" in the ground, for closing cor. to Tps. 20 & 21 S., R11W., marked T20S S31 on N.; CC R11W on E.; T21S S6 on S. faces, with 6 notches on N., S., and E. faces; from which

A Fir 40" dia., bears N.6°E., 32 lks. dist. mkd. T20S R11W S31 BT.

A Spruce 5" dia., bears S.62°E., 40 lks. dist. mkd. T21S R11W S6 BT.

A Fir 40" dia., bears N.43°W., 31 lks. dist. mkd. C C T20 & 21 S R11W BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, E. West, crew - March 1967 - C.S. File 54/1-33

-----  
Found - Orig. 40" now 22" Fir stump, N.6°E., 21.1 ft., shows "S R11W S" on opened blaze. Tree probably 14" when mkd. Ring count 60+ years.

Orig. 40" now 48" Fir, tipped out stump laying face down, N.42°W., 20.5 ft.

No trace of SE BT.

Set brass cap at cor. mkd.

County Surveyors Office

T 20 S	CC	S 31	R11W
T 21 S	R12W	S 6	

1967

New BT - 30" D.Fir stump S.20°E., 6.3 ft. mkd. T21S R11W S6 CC CS BT.

No other stumps or trees close.

This corner lies on very steep NE. slope, approx. 195 ft. South of Twp. Cor. for T20 & 21S R12W. Brass cap is set on East side and under 30" log.

Fd. OK March 1980 by R. Hintz - M 79-30

Survey by John C. Bentley - For: I.P. Timberlands Operating Co., Ltd. - Feb. 1995 - M 121-68

-----  
(Original closing township corner)

Found - 2½" DCSO brass cap on a 1½" iron pipe.

20" Fir stump N.6°E., 20.4 ft. (Rec. 21.1 ft.)

32" Fir stump N.19°E., 6.7 ft. (Rec. S.20°E., 6.3 ft.)

Uprooted Fir stump N.43°W., 18.0 ft. to root hole. (Rec. 20.5 ft.)

(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION CC Tsp. 20 & 21 S. R11W

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs -14" Spruce S.20°E., 34.5 ft. scribed "T21S R11W S6  
CC BT."  
13" Alder N.44°W., 2.5 ft. bark scribed "S1 BT".

Survey by John C. Bentley - For: I.P. Timberlands Operating  
Co., Ltd. - Feb. 1995 - M 121-68  
-----  
(Amended closing township corner)  
Set 2" brass cap on 2" iron pipe for amended closing corner.  
Cap is stamped "T20S R11W S31 CC S6 T21S S1 R12W 1995 LS  
2656"  
New BTs -12" Alder N.71°E., 27.7 ft. bark scribed T20S R11W  
S31 CC BT.  
18" Hemlock S.39°W., 45.3 ft. scribed "S1 BT"  
8" Spruce N.84°W., 28.3 ft. chopped "X".  
County Surveyors brass cap per C.S. File 54/1 bears  
N.89°29'E., 4.97 ft.

Stephen Stys - For: Rayonier - 7/2023 - M182-51  
-----  
(1995 Amended closing township corner)  
Found - A 2" brass cap on a 2" iron pipe with cap marked as  
shown and set per map file M121-68.  
A brass cap bears N.89°29'E 4.97'  
An 11' Alder stump with tag bears N.71°E 27.7'.  
A 34" Hemlock stump, with healed face and tag bears  
S.39°W., 45.3'.  
A 13' Spruce stump 4' tall, with no visible marks  
bears N.84°W., 28,3'.  
LAT. and LONG. Per GARMIN ETREX hand held GPS:  
N: 43°46'56.9" W: 124°03'55,4"