

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5; 32 & 33, T20-11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 116)

-----  
 A Fir 4" dia., which I marked T20S S33 on NE.; R11W S4 on SE.; T21S S5 on SW.; S32 on NW. sides, with 2 notches on W. and 4 notches on E. sides, for cor. to secs. 4, 5, 32 and 33, from which

- A Fir 33" dia., bears N.75°E., 43 lks. dist. mkd. T20S R11W S33 BT.
- A Fir 5" dia., bears S.8½°E., 8 lks. dist. mkd. T21S R11W S4 BT.
- An Alder 5" dia., bears S.66°W., 11 lks. dist. mkd. T21S R11W S5 BT.
- A Fir 4" dia., bears N.1°W., 18 lks. dist. mkd. T20S R11W S32 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Sept. 1964 - C.S. File 53/66-52

-----  
 Found - 58" old Fir stump, N.75°E., 28.4 ft., cut open and found good scribing "S" and "11W".

No trace of corner tree or any other BTs.

Set Brass cap at cor. mkd: County Surveyors Office  
 T20S R11W S 32 | S33  
 T21S R11W S 5 | S 4

1964

- New BTs -7" Hemlock S.83°E., 12.7 ft. mkd. T21S R11W S4 CSBT
- 16" Hemlock S.85°W., 30.8 ft. mkd. T21S R11W S5 CSBT
- 18" D.Fir N.58°W., 30.3 ft. mkd. T20S R11W S32 CSBT
- 11" Hemlock N.62°E., 20.3 ft. mkd T20S R11W S33 CSBT

Note - Corner is approx. 250 ft. south of centerline of new logging road.

Fd. OK, March 1967 by V. Tracy, DCSO

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Pete Earle; Mike Tompkins, crew - Dec. 15, 1976 - C.S. File 59/26-23

-----  
 Found - 1964 DCSO brass cap, firmly in place, 4" above ground, on South edge of a 5" Hemlock stump.  
 Orig. 33" now 58" Fir stump bears N.75°E., 28.4 ft. (to face). Tree has opened blaze, scribing no longer legible, fragmentary reverse scribing found.

(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5; 32 & 33, T20-11

| Alias | Description |
|-------|-------------|
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |

7" Hemlock bears S.79½°E., (Rec. S.83°E.) 12.7 ft. Tree double blazed partially healed, scribing visible "R11W S4 CS". This tree is now a dead snag.

16" now 21" Hemlock bears S.87°W., (Rec. S.85°W.) 30.8 ft. Tree double blazed, partially healed, scribing visible "2 S R B"

18" now 22" D.Fir bears N.57°W., (Rec. N.58°W.) 30.3 ft. Tree has a well healed double blaze.

11" Hemlock bears N.65½°E. (Rec. N.62°E.) 20.3 ft. Tree has opened double blaze, visible scribing "20S R11 S33 CS BT". Tree is dying.

New BTs -11" Hemlock bears S.76½°E., 23.0 ft. Tree double blazed and scribed "T21S R11W S4 CS BT".

10" Hemlock bears N.72°E., 42.5 ft. Tree double blazed and scribed "T20S R11W S33 CS BT"

Fd. OK May 19, 1980 by E. Alvarado - C.S. File 61/6-45