

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1158)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Willow 4" dia., bears S.50°E., 71 lks. dist. A Spruce 5" dia., bears N.38°E., 134 lks. dist.</p>
<p>GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page 1222 and Page 1224)</p> <p>-----</p> <p>(Page 1222) The ¼ sec. cor. bet. secs. 21 and 28, having been destroyed and all marks of bearing trees obliterated. (Page 1224) Set a post, 4 ft. long, 5" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on N. face, from which A Spruce 12" dia., bears N.52½°E., 100 lks. dist. mkd. ¼ S BT. An Alder 8" dia., bears N.37½°W., 140 lks. dist. mkd. ¼ S BT. And raised a mound of stone, 1½ ft. high, 2 ft. base alongside. The former bearing trees have been destroyed by fire, as a logging road is opened through here.</p>
<p>BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #430, Surveyed June/Aug. 1960 (DCSO records Vol. 31 Page(s) 12903)</p> <p>-----</p> <p>Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, in shoulder of road, with brass cap mkd: ¼ <u>S 21</u> S 28 T 21 S R 11 W 1960</p> <p>from which A Fir 30" dia., bears N.33 3/4°E., 100 lks. dist. mkd. ¼ S21 BT. An Alder 4" dia., bears S.86°E., 74 lks. dist. mkd. ¼ S28 BT.</p>
<p>Fd. OK, Feb. 1984 by J. Prochnau - M 96-63 A & B</p>
<p>1</p>