

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; and 35 of T20-11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 1 Page(s) 85 (and duplicate page 1165))

Set ¼ sec. post, from which
A Cedar 12" dia., bears S.10°W., 18 lks. dist.
A Bearberry, 4" dia., bears N.47°W., 34 lks. dist.

H.L. Eppstein, Co. Surveyor - Wit: F. Cain and Harry Henderson - Jan. 24, 1929 - (No source record, see "old" corner book, Page 7)

Set a Chittam post 4"x4"x3½ ft. by orig. BT. to witness..
Cedar 12", S.18°W., 18 lks., decayed but marks plain.
Other BTs destroyed.
Marked new BTs:
Fir 10" bears S.82°W., 17 lks.
Fir 16" bears N.46°W., 18 lks.

Douglas County Surveyors Office - Milo E. Godfrey and crew - Sept. 1964 - C.S. File 53/66-53

Found - ¾" Iron pipe.
52" Red Cedar S.10°W., 12.0 ft. previously opened through rotten wood on South side, good reverse scribing visible on overgrowth of old face.
Fir stump S.82°W., 11.2 ft., cut open below markings Eppstein's other BT destroyed by road construction.
New BTs - 23" Red Cedar N.52°E., 34.4 ft. mkd. ¼ S35 CS BT.
52" Red Cedar S.10°W., 12.0 ft. mkd. ¼ S2 CS BT.
(Orig. BT)
Corner is on top edge of cut bank on E. side of Smith River Road.

Fd. OK May 12, 1980 by E. Alvarado - C.S. File 61/6-40

Survey by Bruce A. Shaner - For: Moore Mill & Lumber Co. - July 1981 - RM 3-48

Set Brass cap mkd. T20S R11W WM 1/4 S35 S2 T21S RLS 430 1981. I reset the found ¾" I.P. alongside.
Found - 56" W.Red Cedar, (orig. BT) with scribes visible, bears S.10°W., 12.0 ft.
24" W.Red Cedar with scribes visible, bears N.58°E., 34.5 ft.

Fd. OK Dec. 1990 - M 111-47 A-F