

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1166)

Set stone 12x10x5 for cor. to secs. 1, 2, 11 and 12, from which
A Fir 30" dia., bears N.25°E., 30 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1195-96)

Having been informed that the cor. to secs. 1, 2, 11 and 12 has been destroyed by fire,
Set a sandstone 12x10x8 ins. for cor. marked with 5 notches on S. and 1 on E. edges, from which
A Fir 24" dia., bears N.88½°E., 20 lks. dist. mkd. T21S R11W S1 BT.
A Cedar 12" dia., bears S.4°E., 44 lks. dist. mkd. T21S R11W S12 BT.
A Fir 27" dia., bears S.73½°W., 15 lks. dist. mkd. T21S R11W S11 BT.
A Fir 12" dia., bears N.50½°W., 52 lks. dist. mkd. T21S R11W S2 BT.
This cor. stands on top of a boulder, 5 ft. sq., and 3 ft. above ground; spot also marked with a cross.

Survey by Bruce A. Shaner - For: Moore Mill & Lumber Co. - July 1981 - RM 3-48

Found - 12" x 10" x 5" stone.
44" D.Fir snag, orig. BT, with rotten face, bears N.25°E., 19.8 ft.
Set Brass cap in place of stone mkd. "T21S R11W WM S1 S2 S11 S12 RLS 430 1981".
New BTs -36" D.Fir, I scribed "T21S R11W S2 BT" bears N.32½°W., 21.0 ft.
14" W.Red Cedar, I scribed "T21S R11W S1 BT", bears N.61°E., 21.0 ft.
30" W.Red Cedar, I scribed "T21S R11W S11 BT", bears S.14°E., 30.1 ft.
26" Hemlock, I scribed "T21S R11W S11 BT", bears S.45°W., 4.6 ft.
Reset the stone alongside brass cap.
Corner is at the intersection of E-W and N-S very old blazed lines, timber cutting lines.
Haines tag is at corner as well as cruiser mark "SR".