

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John W Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Pg 1166)

-----  
Set ¼ sec. post, from which  
A Spruce 12" dia., bears N.65°E., 31 lks. dist.  
A Cedar 7" dia., bears N.45°W., 48 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1195)

-----  
The ¼ sec. cor. bet. 1 and 2; which having been destroyed, I replace by setting a post, 3 ft. long, 3" sq. for ¼ sec. cor. mkd. ¼ S on W. face, from which  
A stump of Cedar 10" dia., bears N.45°W., 48 lks. mkd. BT.  
This is the only remnant of former survey.  
A Cedar 10" dia., bears S.43°E., 34 lks. mkd. ¼ S BT.

B. A. Lane - April 14, 1938 - C.S. File 19/18A

-----  
Found old stake mkd. ¼ C.S.  
Set steering gear of an auto.  
Old stump decayed to badly to identify checks for dist. and bearing.  
Orig. 10" Cedar, burned badly, no scribe. Marks visible.  
Checks Brg. & Dist., remarked ¼ S CS BT.  
30" Cedar S.43°E., 26 ft.  
8" Alder S.28°W., 17½ ft.

Survey by Richard J. Hintz - For: International Paper Co. - Feb. 1984 - M 96-5

-----  
Found 1/2" I.P. with alum. alloy fixture (origin unknown) from which:  
50" Cedar bears S.44°30'E., 19.9 ft. (1891 BT Rec. S.43°E., 22.4 ft.)  
New BT, 28" Cedar S.81°30'W., 44.7 ft., scribed.

Douglas Co. Surveyors Office - Kris DeGroot, Co. Surveyor - Stephen Flause, Jeff Lorsung - June/July 2021 - M178-44 & C.S. 67/51-4

-----  
Found - A 3/4" (I.D.) iron pipe as found by R.J. Hintz in 1984, firmly set and buried 4" below the ground surface with the alloy fixture now missing.  
Set - The 3/4" iron pipe was referenced and at its precise position a 1"(I.D.)x30" iron pipe was set 23" in the ground with a 2½" dia. brass cap STAMPED:  
continued next page

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

DOUGLAS COUNTY SURVEYORS OFFICE

$\frac{1}{4}$   
T21S R11W  
S2 | S1  
2021

The 3/4" iron pipe was reset 0.2 ft. NW and flush with the ground. This corner falls on a steep NW slope in timber approximately 250 ft. SE of the left (Southerly) bank of the Smith River and 100 ft. SE of the toe of the slope and river bench. From which a BT by Thiel, USGLO Deputy Surveyor, in 1891- A 58" diam. R.Cedar bears S.44°30'E., 19.9 ft. with healed blaze. (matches Hintz's M 96-5 record)  
A BT by R.J. Hintz in 1984 per M 96-5 -  
A 50" diam. R.Cedar bears S.81°30'W., 44.4 ft. with a partially healed rotted blaze rescribed "CS BT" with a 8" mag hub nail in the root crown (rec. 44.7 ft.)  
New BTs- A 39" diam. R.Cedar bears N.4°E., 40.5 ft. scribed " $\frac{1}{4}$  S1" "CS BT" on a double blaze with a 4" mag hub nail.  
A 16" diam. alder bears S.20°W., 27.4 ft. bark scribed " $\frac{1}{4}$  S2 CS BT" with a 4" mag hub nail.  
Note - Corner is on a steep NW slope in timber approx. 250 SE of southerly bank of Smith river & 100 ft. SE of toe of slope & river bench.  
Compass decl. 15°E.  
Lat: 43°14'29.9" N Long: 123°58'01.3" W