

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1297)

Set ¼ sec. post, from which
 A Fir 36" dia., bears S.85°E., 20 lks. dist.
 A Fir 16" dia., bears N.65°W., 9 lks. dist.

Survey by W.G. Corbitt; H. hendrickson - For: Crown Zellerbach - July 24, 1943 - C.S. File 52/91

Found both bearing trees to ¼ corner, and relocated corner with 1½" I.P. and 2x2x5 ft. Fir post, crayon mkd. "¼S S5 S4 July 24, 1943", from which bears
 Orig. 36" D.Fir now 4 ft., S.83°E., 13.2 ft. to nail scribed ¼ S (BT covered)
 Orig. 16" D.Fir now broken off snag, 8 ft. tall, N.73°W., 5.94 ft. to nail scribed ¼ S BT.
 I crayon mark 3 ft. D.Fir N.73°W., 10.5 ft. "RP BT ¼ S5"
Corner stands on South slope of small ridge course E & W.

Fd. OK by Ore. St. Hwy. Dept. in 1952 - DCSO records "D-3"

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 1198)

The ¼ sec. cor., perpetuated and recorded by Corbitt in 1943, monumented with an iron pipe, 1½" dia., firmly set, flush with the surface of the ground, from which the remains of an original bearing tree
 A Fir snag 16" dia., bears N.65°W., 9 lks. dist. with scribe marks ¼ 5 BT visible on open blaze.
At the corner point
Set an aluminum post 28" long, 2½" dia., 24" in the ground with alum. cap mkd:
 T 21 S R 12 W
 1/4
 S 5 S 4
 1981
from which new bearing trees
 A Spruce 7" dia., bears N.66½°E., 25 lks. dist. mkd. ¼ S4 BT.
 A Spruce 23" dia., bears N.41°W., 27½ lks. dist. mkd. ¼ S5 BT.
Reset iron pipe alongside aluminum post.

Found OK by C. Blevins, July 2000 - M136-27C

