

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. 33 & 34; and 3 & 4, T22-12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCS0 records Vol. 3 Page(s) 1263)

Set post cor. of secs. 3, 4, 33 and 34, from which
A Spruce 24" dia., bears S.85°W., 18 lks. dist.
A Spruce 20" dia., bears N.29°W., 52 lks. dist.
An Alder 12" dia., bears N.17°E., 10 lks. dist.
A Vine Maple 4" dia., bears S.40°E., 18 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, John M. Powell & J. Brady - Aug. 24, 1967 - C.S. File 54/46-5

Found - No trace of Iron pipe at section corner.
Orig. 24" Spruce, now 36" rotted stump, S.85°W., 11.9 ft. scribe visible "S4 22 R12W."
Orig. 20" Spruce now 24" rotted stump N.29°W., 34.3 ft. scribing found "R12W T22."
No trace of NE or SE BTS.
Distances from orig. BTS taken from face.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 12 W
S 33 | S 34
S 4 | S 3
T 22 S
1967

Brass cap in 12" x 24" tile which is filled with concrete.
New BTS -38" Spruce N.40°W., 83.6 ft. mkd. T21S R12W S33 CSBT
38" Hemlock N.73°E., 90.0 ft. mkd. T21S R12W S34 CS
BT.
Power pole, bearing object, S.50°W., 110.7 ft.
P #AG04A-34

This corner lies in middle of draw running E. and W. Also North of Forest Hills Road or 22nd., approx. 125.0 ft.

Fd. OK, Feb. 12, 1975, DCS0, L. Monrean - C.S. File 59/46-35

Fd. OK, Oct. 1987 by R. Stuntzner - M 101-28
Fd. Ok, July 1996 by J. Estabrook - M 125-35
Fd. Ok, Aug 1997 by J. Estabrook - M 127-49
Fd. as per record, 3/2016 - M170-54 A-E

Fd BC atop 12" dia., concrete pedestal, cap 0.2 ft above concrete and concrete flush with surface, good condition - E. Hibbs, ODOT - Filed 11/2020 - ST Hwy 38-036A

continued next page

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. 33 & 34; and 3 & 4, T22-12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 8/19/2025 - C.S. File 67/61-15

Found - 2½" D.C.S.O. brass cap in 12"x24" tile filled with
concrete cap up 2"

Very rotted 36" spruce stump S.85°W. 11.9ft

Very rotted 24" spruce stump N.29°W 34.3ft

56" spruce N.40°W. 83.8ft fully healed double blaze

Light pole S.50°W. 110.7ft P#AG04A-35

Alum post with land surveying monument sign south 1.0ft

County Surveyors Office

T 21 S R 12 W

S 33 | S 34

S 4 | S 3

T 22 S

1967

Compass decl. 14¼°E.

Trimble GEO XT Position

43°41'50.338" N.

124°07'26.313" W.