

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCS0 records Vol. 3 Page(s) 1269)

-----  
Set ¼ sec. post, from which  
An Alder 15" dia., bears S.50°W., 10 lks. dist.  
An Alder 12" dia., bears S.32°E., 16 lks. dist.

Survey by Richard J. Hintz, LS #497 - For: International Paper Co.; Menasha Corporation; U.S. Forest Service - Nov. 1980 - M 84-24 A&B

-----  
Corner falls on West shoulder of Smith River County Road #48, NOT SET.

Reference monuments:  
2" alum. pipe with stamped alum. cap bears N.0°13'10"E., 30.0 ft.  
2" alum. pipe with stamped alum. cap bears N.89°46'50"W., 30.0 ft.

Richard Hintz, for Internat'l Paper Co. Sept. 1987 - M104-67

-----  
Note - The position for the SE corner of Section 26 was incorrectly established by double proportion per M 84-24 which moved the position of the computed 1/4 corner in relation with the reference monuments.

Reference monuments now bear:  
2" alum. pipe with stamped alum. cap bears N.6°02'18"E., 30.17 ft.  
2" alum. pipe with stamped alum. cap bears N.89°45'12"W., 26.94 ft.

Fd. OK - Clyde Mulkins - April 1996 - M 125-11

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - July 15, 2019 - C.S. File 67/49-4

-----  
The corner position falls in the NW shoulder of Smith River Co. Rd No. 48. no monument is set at true corner position per M84-24 or M104-67 found two reference monuments per M84-24 with 3¼" aluminum caps marked as follows

USDA FOREST SERVICE	USDA FOREST SERVICE
PLS 497	PLS 497
RM ¼	RM ¼
S26 \ S25	----- S26 \
1980	1980
T21S R12W	T21S R12W

continued next page

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

No evidence of original BTs by Gordon in 1857.  
Reference monuments by Hintz in 1980 per M84-24:  
A 2" I.D. aluminum pipe firmly set flush with the ground bears N.06°02'18"E., 30.17 ft with a carsonite guard post alongside.  
A 2" I.D. aluminum pipe firmly set flush with the ground bears N.89°45'12"W., 26 94 ft. with a carsonite guard post alongside.  
New - A 4" mag hub projecting 1" above the top of a 4"x6"x2' tall guardrail post located on the east side of the road bears S.04°53'W., 82.21 ft.  
Note- The corner falls in the NW shoulder of Lower Smith River Rd.  
Basis of bearing: M104-67  
compass declination: 14¾°E.