

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 3 Page(s) 1343)

Set 1/4 sec. post, from which
A W.Oak 8" dia., bears N.40°W., 58 lks. dist.
A W.Oak 7" dia., bears S.80°E., 39 lks. dist.

Present: A.E. Jones; A.J. Lee; Cutlack Bros. - Jan. 10, 1900
Volume 2 Page 261

Set a Fir post, from which
A Fir 60" dia., bears N.10°E., 80 lks. dist.
A Fir 30" dia., bears S.23°W., 174 lks. dist.
Both original BTs are still standing but killed by fire years ago, liable to fall.

Kenneth P. McReynolds, LS #277 - Feb. 1955 - C.S. File 41/340

1/2" Bolt at corner.
Found 1 Fir BT, 60" dia., remaining but all scribe had been burned out, however, this tree is N.10°W., not N.10°E. as described in the notes. Bert Cutlack was present and he was also present almost exactly 50 years ago when the re-survey was made and has lived in the immediate vicinity ever since. He stated that this Fir had always been considered the BT.
I Scribed:
A Madrone 14" dia., which bears N.61°30'E., 87.0 ft. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - M. Godfrey; S. Bilow, crew - May 12, 1958 - C.S. File 49/59-20

Found - Now 60" R.Fir bears N.10°W., 52.8 ft. I find no scribing, but old axe scar faces to corner and I find clump of W.Oak that checks bearing and distance for orig. NW. BT.
Also find bottom section of old charred stake 24" under surface at corner.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 4 W
1/4 S8 | S9
1958
New BTs -24" R.Fir bears N.77°E., 65.0 ft. scribed S9 CS BT
24" R.Fir bears N.19°W., 30.2 ft. scribed S8 CS BT
I find 3/4" I.P. at corner and Laurel BT as recorded, 1955.

(Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Glen McChesney - For: Weyerhaeuser Co. - June 26, 1959 - C.S. File 53/105-3</p> <p>-----</p> <p>Added "W" nails and plates to County BTs.</p>
<p>Cor. Fd. and used in BLM resurvey by Donald Beck under Group #516, surveyed July/Aug. 1963 (DCSO records, Vol. 32 Page 13429)</p>
<p>Cor. Fd. OK, Sept. 1992 by D. Peel - M 115-77</p>
<p>BLM resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1935, surveyed Jan./Feb. 2000 - (DCSO rec. Vol. 53 Page(s) 20380-1)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 8 & 9, monumented with an iron post 1¼" diam., firmly set, projecting 5" above ground (alongside of which is a bent iron pipe, ½" diam., firmly set, projecting 4" above ground), with properly marked brass cap. from which the remains of bearing trees mkd. by Byron</p> <p> A sawed fir stump, 40" diam., bears N.77½°E., 65.3 ft., with a healed double blaze.</p> <p> A fir, 33" diam., bears N.20°W., 30.4 ft., with a healed double blaze.</p> <p>and a new bearing tree</p> <p> A fir, 6" diam., bears S.1 3/4° 94.0 ft., mkd. ¼ S9 BT.</p> <p>Corner is located on top of ridge, bears N.50°E. and S.50°W. Each new bearing tree has a 2½ in. X ¼ in. magnetic nail (Mag Nail) driven at the base on right side-center</p>
<p> </p>