

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 and 32 & 33 T21-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 752)

-----  
Set post cor. of secs. 4, 5, 32 and 33, from which  
A Fir 15" dia., bears S.36°E., 13 lks. dist.  
A Fir 8" dia., bears S.66°W., 73 lks. dist.  
A Fir 10" dia., bears N.50°E., 12 lks. dist.  
A Yew 6" dia., bears N.25°W., 27 lks. dist.

Fd. and used by Wm. P. Wright in GLO survey, under Contract #514, dated Aug. 27, 1884 (DCSO records, Vol. 4 Page 1364)

W.F. Briggs - Wit: Pete Matchatte and S. Tonalee - March 16, 1901 - Vol. 2 Page 263

-----  
Found - Stake badly decayed.  
Orig. BT, down and destroyed except the Yew tree and it was down, marks visible.  
Set new post, Yew, 4 x 4 ins., sq., 3½ ft. long, from which  
6" Fir bears N.7½°E., 23 lks.  
6" Fir bears N.37½°W., 21 lks.  
5" Fir bears S.32°E., 21 lks.  
No tree near in SW.

Milo E. Godfrey and crew - Oct. 23, 1964 - C.S. File 49/68-17

-----  
Found - Small Fir snag, N.7½°E., 15.2 ft., scribing visible on badly rotted, exposed face, "T21SR4WS33" BT. scar vsibile.  
No other BTs found.

Set Brass cap at cor. mkd: County Surveyors Office  
R4W T21S S32|S33  
T22S S 5|S 4  
1964

New BTs -9" D.Fir N.2°E., 89.6 ft. mkd. T21S R4W S33 CS BT.  
17" D.Fir N.25°W., 12.0 ft. mkd. T21S R4W S32 CSBT  
7" Hemlock S.72½°W., 24.8 ft. mkd. T22S R4W S5 CSBT  
No trees convenient SE. of corner.

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1026, surveyed July 15, 1980/March 12, 1981 (DCSO records Vol. 44 Page(s) 16956)

-----  
The sec. cor., perpetuated and recorded by Briggs, Deputy Co. Surveyor in 1901, from original evidence no longer in existence, and further perpetuated and recorded by Godfrey in (Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec Cor for 4 & 5 and 32 & 33 T21-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1964, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground with mkd. brass cap.  
from which the remains of a bearing tree mkd. by Briggs  
A Fir stump 9" dia., bears N.7½°E., 23 lks. dist. with decayed blaze, no marks visible.  
and bearing trees mkd. by Godfrey  
A Fir 10" dia., bears N.¾°E., 136 lks. dist. with healed blaze.  
A Hemlock 17" dia., bears S.72¼°W., 36½ lks. dist. with healed blaze.  
A Fir 20" dia., bears N.25°W., 18½ lks. dist. with healed blaze.  
and a new bearing tree  
A Fir 6" dia., bears S.35½°E., 39 lks. dist. mkd. T22S R4W S4 BT.

David Wellman - For: Summerwood Inc. - June 1999 - M 132-12  
-----

Condition report  
Found - Douglas Co. brass cap dated 1964, 0.8 ft above ground.  
13" Fir, N.2½°E., 89.6 ft. to nail set side center - closed face - rec: N.2°E., 89.6 ft. 1964 DCS0  
28" Hemlock, S.74°W., 24.4 ft., to nail set side center - closed face - rec: S.72½°W., 24.8 ft. 1964 DCS0  
28" N.23½°W., 12.1 ft. to nail set side center - closed face - rec: N.25°W., 12.0 ft. - 1964 DCS0  
11" Fir, S.34½°E., 32.4 ft. to nail set side center - closed face - rec: S.35½°E., 39 lks., 1980 BLM  
Note - Downed fence runs West.

Fd. BC 7/2014 by D. Edwards - M168-28