

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1344)

Set ¼ sec. post, from which
A Fir 20" dia., bears S.7°W., 9 lks. dist.
A Cedar 9" dia., bears N.13°E., 1510 lks. dist.

Douglas County Surveyors Office - James W. Byron, Deputy - M. Godfrey; S. Bilow, crew - May 12, 1958 - C.S. File 49/59-21

Found - Orig. 9" now 40" Cedar N.13°E., 9.9 ft., has good scribing on old face "¼S", rec. dist. is 1510, should be 15 lks.

Rotted base of large Fir that would check for orig. SW. BT, no scribing found.

There is a 4" x 4" sq. stake with scribing at cor.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 4 W

¼ S 4

S 9

1958

New BTs -5" W. Fir bears S.29½°W., 25.0 ft. scribed ¼ S9 CS BT
I rescribe orig., now 40" Cedar N.13°E., 9.9 ft.,
scribed "¼ S4 CS BT"

This area has many large trees near that were standing at the time of the orig. survey. There may be error in recording distance to orig. NE. BT.

Glen McChesney - For: Weyerhaeuser Co. - April 2, 1959 - C.S. File 53/105-1

1855 GL0 survey record:

Post, no trace of original.

20" Fir S.7°W., 9 lks.; found rotted, down Fir, hard to identify.

9" Cedar N.13°E., 1510 lks.; 38" I.Cedar, orig. scribing visible, newly scribed.

1958 County record:

Found brass cap dated 1958.

38" I.Cedar scribed "¼ S4 CSBT"

4" W. Fir scribed "¼ S9 CS BT"

Accessories added: (plates and "W" nails)

38" I.Cedar, N.10°E., 8.9 ft. (GL0 and County)

38" I.Cedar S.25°W., 32.2 ft.

Cor. and BTs still in good condition Oct. 23, 1962, after big windstorm. Milo E. Godfrey C.S. File 49/59-36 cont.

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. Fd. and used in BLM resurvey by Donald Beck, under Group #516, surveyed July/Aug. 1963 (DCSO Record Vol. 32 Pg.13431)

Corner report by Daniel Baker - C.S. 63/154-25 - 5/13/94

Found - Douglas County Brass Cap Dated 1958 - good cond.
38" Cedar, N.14°E. 15 lks., - 1855 BT (uprooted)
18" W.Fir, S.30°W. 25.3' - 1958 Do. Co. - rec.
S.29½°W., 25.'
38" Cedar, S.25°W. 32.2' - 1959 Weyerhaeuser -
updated & log removed.

New Accessories -

10" D.Fir, N.17°E. 20.2' to "W" Nail.
15" W.Fir, N.62°W. 9.7' to "W" Nail.
21" W.Fir, N.84°E. 19.5' to "W" Nail.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1935, surveyed Jan./Feb. 2000 - (DCSO rec. Vol. 53 Page(s) 20378-9)

The ¼ sec. cor. of secs. 4 & 9, monumented with an iron post, 1¼" diam., firmly set, projecting 16" above ground, with properly marked brass cap, from which the remains of an original bearing tree

A roothole, bears N.14¼°E., 9.9 ft., alongside of which is the decayed cedar trunk, 26" diam., with no marks visible on decayed face.

and a bearing tree mkd. by Byron

A fir, 22" diam., bears S.29½°W., 24.9 ft., with a healed double blaze. (Record 21.8 ft.)

and the remains of a bearing tree mkd. by McChesney, in 1959,

A sawed and decayed cedar stump, size indeterminate, bears S.25°W., 32.2 ft., with no marks visible.

and bearing trees mkd. by Baker, in 1994, recorded in the Douglas County Surveyors Office, C.S. File No. 36/154 {There was an error in our records C.S. File No. should be: 63/154}

A fir, 12" diam., bears N.12¼°E., 21.3 ft., with fragmentary scribe marks visible on partially healed blaze.

A fir, 25" diam., bears S.87 ¾°E., 20.6 ft., with fragmentary scribe marks visible on partially healed blaze.

A fir, 20" diam., bears N.62½°W., 11.0 ft., with fragmentary scribe marks visible on partially healed blaze.

continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor,
and Robert H. Browning, Surveying Tech. Group No. 2170
surveyed Aug 2007/Feb 2008 - (DCSO recs Vol. 55 Pgs 21815-6)

The ¼ sec. cor. of secs. 4 & 9, monumented with an iron post,
1¼" dia., firmly set, projecting 15" above ground, with brass
cap (properly) mkd.

from which the remains of an original bearing tree
A root hole bears N.14°E., 9.9 ft., with fallen cedar
trunk, size indeterminate, lying alongside, no marks
visible on decayed face.

and the remains of a BT mkd. by Byron, in 1958, reported by
Skeesick and Browning

A fir, 24" dia., bears S.28½°W., 24.9 ft., with a healed
double blaze.

and BTs mkd. by Baker, in 1994, reported by Skeesick and
Browning

A fir, 13" dia., bears N.12¼°E., 21.3 ft., with a healed
double blaze.

A fir, 28" dia., bears S.87¾°E., 20.6 ft., with a healed
blaze.

A fir, 21" dia., bears N.62½°W., 11.0 ft., with a healed
double blaze.