

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1336)

Set ¼ sec. post, from which
A Fir 20" dia., bears S.22°W., 25 lks. dist.
A Fir 7" dia., bears S.84°E., 13 lks. dist.

Floyd Cole, Deputy Co. Surveyor - Wit: C.F. Andrew and O.A. Parker - April 5, 1915 - Vol. 2 Pages 202-4; Field Book 40 Page 14 - (and "old" cor. renewal book, Vol. 1 Pg. 17)

No evidence of old witness trees. Marked:
A Maple 24" dia., S.74½°W., 83 lks.
A W.Oak 8" dia., S.49°E., 62 lks.

O.F. Thiel - For: Olif May - Nov. 14, 1947 - Thiel's Field Book 4 Page 24

Yew fence post in place. Stumps of old trees still there.

Searched for, not fd - DCSO, Dec. 1964 - C.S. File 53/101-57

Corner report by Donald Peel - For: Weyerhaeuser Co. - July 8, 1988 - M 106-59

There was no original evidence of the West 1/4 Cor. Sec. 34 and the bearing trees established by Cole in 1915 were both gone. There was an old Yew wood post at the intersection of an existing N-S fence and a fence running East. I accepted the yew wood post at the fence corner as being the best evidence possible of the ¼ cor. as re-established by Cole.

Fd. Yew Wood post, June 8, 1990 by D. Peel - M 110-39