

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 3 Page(s) 1338)

Set ¼ sec. post, from which
A Cedar 12" dia., bears N.58°E., 19 lks. dist.
A Fir 30" dia., bears S.55°W., 46 lks. dist.

Douglas County Surveyors Office - James W. Bryon, Deputy - M. Godfrey and S. Bilow, crew - May 12, 1958 - C.S. 49/59-23

Found - Orig. 12" now 36" Cedar N.58°E., 12.5 ft., has good reverse scribing on large chip cut out 2 or 3 years ago.

I find hole in ground that checks bearing and distance for orig. SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 4 W
¼ S9 | S10
1958

New BTs -I rescribe now 36" Cedar, N.58°E., 12.5 ft. "¼ S10 CS BT"
13" R.Fir S.41°W., 47.1 ft. scribed "¼ S9 CS BT"

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #516 -Surveyed July 29/Aug. 23, 1963 - (DCS0 records Vol. 32 Page(s) 13423-24)

(Corner Report only)
Cor. of Secs. 9 and 10, perpetuated and recorded by Byron in 1958, monumented with an iron post, 1" dia., firmly set, protruding 12" above ground with mkd. brass cap., from which the remaining original bearing tree:

A Cedar 37" dia., bears N.58°E., 19 lks. dist., mkd. ¼ S in negative on overgrowth. Remarkd ¼ S10 CS BT by Bryon in 1958.

and a tree mkd. by Bryon:

A Fir 13" dia., bears S.47½°W., 70 lks. dist. mkd. with a healed double blaze.

William L. Wilt - For: Weyerhaeuser Co. - May 29, 1964 - C.S. File 53/105-10

Added "W" nails and plates to:
36" I.Cedar (Orig. BT) rescribed 1958 by DCS0, N.59°E., 11.9 ft. (face chopped out, face rotted but chip shows good negative scribing)
(Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

13" D.Fir S.41°W., 46.3 ft. (1958 County BT), good condition, face healed over.

Douglas County Surveyors Office - L.E. Monrean, Deputy - S. Flause; R. Smith, crew - Aug. 2, 1984 - C.S. File 62/18-7

Found - 1958 DCS0 brass cap on a 1" x 36" long galv. I.P. Monument removed by construction of fire trail is found lying S.42°E., 7.6 ft. from corner position. I.P. rusted near top.

An orig. Cedar 12" dia., now a Cedar stump 36" dia. and 60" tall, bears N.58°E., 12.5 ft. No orig. scribing found. Byron rescribe has open face and shows scribing "¼ S10 CS BT".

No evidence of other orig. BT found.

A 13" R.Fir now a 17" DBH D.Fir bears S.41 3/4°W., 46.4 ft. (Rec. per Byron, S.41°W., 47.1 ft.; BLM rec. S.47½°W., 46.2 ft.)

Found monument is replaced by new cap and pipe because of its rusted condition. Position for new mon. determined primarily from record brg. and dist. from found orig. BT.

SET a 2 3/8" brass cap on a 1" x 32" I.P. firmly set and protruding 7" from ground. Cap mkd: "Douglas Co. Surveyors Office T22S 1/4 S9 S10 R4W 1984".

New BTs -9" DBH D.Fir bears S.57½°E., 17.0 ft. scribed "¼ S10 CS BT" on a double blaze.

13" DBH D.Fir bears S.15°E., 44.8 ft. scribed "¼ S10 CS BT" on a double blaze.

12" DBH W.Fir bears S.76½°W., 22.9 ft. scribed "¼ S9 CS BT" on a double blaze.

Corner is located 80 ft. ± North of ridge top accessed from BLM Rd. 22-4-20.0. (Sketch in CS File)

Fd. & used on BLM resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1935, surveyed Jan./Feb. 2000 - (DCS0 rec. Vol. 53 Page(s) 20379-80)