

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1361)

Set post 4" dia., 4 ft. long with marked stone, 12" in ground for qr. sec. cor., mkd. ¼ S on W. face, from which
A Fir 40" dia., bears S.10°W., 3 lks. dist. mkd. ¼ S BT.
A Fir 14" dia., bears N.80°E., 5 lks. dist. mkd. ¼ S BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under special instructions dated August 15, 1901 (DCSO records Vol. 4 Page(s) 1379)

The ¼ sec. cor., having disappeared, I set a Cedar post 3 ft. long, 3" sq., 24" in the ground, marked ¼ S10 on W. face and 11 on E. face, witnessed as described by the surveyor general, except that S.10°W., should read S.10°E. and N.80°E., should have been S.80°W.

Nov. 13, 1901

Glen McChesney - For: Weyerhaeuser Co. - May 29, 1958 - C.S. File 53/105-4

1884 GLO survey record:
Found stone as described in field notes.
40" Fir S.10°W., 3 lks.; 46" Fir, bark scribing visible both upper and lower face.
14" Fir N.80°E., 5 lks.; hollow spot, possible root hole.
Accessories added this date: ("W" nails and plates)
34" Fir stump N.77°W., 20.7 ft.
38" I.Cedar N.25°E., 22.8 ft.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - Jan. 1965 - C.S. File 53/101-78

Found - Orig. 40" Fir, now 48" stump S.10°E., 2.0 ft., shows bark scribing.
Original stone has been disturbed.
No trace of SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 4 W
¼ S10 | S11
1965

New BTs -18" Cedar S.31°E., 29.0 ft. mkd. ¼ S11 CS BT.
14" Cedar S.61°W., 26.5 ft. mkd. ¼ S10 CS BT.

continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Dave Wellman, LS 2163 - For: Weyerhaeuser Co. - Erin Heatherstone - 1/20/2003 - C.S. File 65/45-11A&B

Found - 2½" DCSO brass cap dated 1965, 0.5 ft. above ground.
48" Fir stump, S.10°E., 2.0 ft. to face.
Rotten 24" Fir stump, N.60°W., 18.5 ft. to "W" nail.
38" I.Cedar 1958 WEYCO tag reads S.25°W., 22.8 ft. -
Down & Out.
32" I.Cedar S.24°E., 29.1 ft. to spike set side
center - close face.
31" I.Cedar S.64½°W., 26.2 ft. to spike set side
center - closed face.
New BTs- 12" Fir S.83°E., 18.0 ft. to spike set side center
- scribed "¼ S11 BT"
14" Fir N.65°W., 12.0 ft. to spike set side center
- scribed "¼ S10 BT"