

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1361)

-----

Set post 6" dia., 4 ft. long with marked stone, 12" in the ground for cor. to secs. 2, 3, 10 and 11, marked T22S S2 on NE.; R4W S11 on SE.; S10 on SW.; S3 on NW. face, with 2 notches on E. and 5 in S. edges, from which

- A Fir 48" dia., bears N.70°W., 8 lks. dist. mkd. T22S R4W S3 BT.
- A Fir 48" dia., bears S.35°W., 7 lks. dist. mkd. T22S R4W S10 BT.
- A Maple 10" dia., bears N.14°E., 41 lks. dist. mkd. T22S R4W S2 BT.
- A Maple 10" dia., bears S.25°E., 47 lks. dist. mkd. T22S R4W S11 BT.

Fd. and used in GL0 survey by O.F. Thiel, under Special Instructions, dated Aug. 15, 1901 (DCSO records, Vol 4 page 1380)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Clete Putnam & Vernon "Ray" Tracy, crew - March 1962 - C.S. File 49/42-53

-----

Found - 24" Maple S.25°E., 31.0 ft. Cut open and found good reverse S scribe "BT" (Center rotted away)

- 48" Fir S.35°W., 6.6 ft. uprooted and down, lying on face.
- 48" Fir N.70°W., 5.3 ft. (SW BT lying against face of NW. tree.) Old axe marks visible in bark above log. Rescribed this tree in bark, above log, "T22S R4W S3 CS BT"

Set Brass cap at cor. mkd: County Surveyors Office

T	22	S	R	4	W
	S	3		S	2
	S	10		S	11
					1962

New BTs -22" R.Cedar S.32°W., 6.0 ft. mkd. T22S R4W S10 CS BT

- 27" D.Fir N.8½°E., 59.3 ft. mkd. T22S R4W S2 CS BT.
- 26" D.Fir S.89°E., 60.6 ft. mkd. T22S R4W S11 CS BT.

Douglas County Surveyors Office - F.L. Ingram, Deputy - R. Tracy & W. Penley, crew - Oct. 8, 1971 - C.S. File 53/101-11

-----

Found - 24" Maple S.25°E., 31.0 ft. Good condition.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

48" Fir S.35°W., 6.6 ft. Uprooted and down.  
22" R.Cedar S.32°W., 61.0 ft. Good condition  
27" D.Fir N.8½°E., 59.3 ft. now stump, good condition.  
26" D.Fir S.89°E., 60.6 ft. Uprooted and down.  
48" Fir N.70°W., 5.3 ft. Uprooted and down.  
Reset brass cap pulled up by windfall. Reset from BTs. No new BTs available.

BLM Resurvey, by Dale B. Bedell, surveyed under group no. 1703. Surveyed Aug. 1993 thru May 1994. D.C.S.O. records Vol. 52 Page 19647.

-----  
Found - Iron post, 1 1/4 ins. diam., firmly set, projecting 12 ins. above the ground, with 1962 D.C.S.O. brass cap properly mkd.  
from which the remains of an original bearing tree  
A maple, 32 ins. diam., bears S.25°E., 47 lks. dist., with axe marks on a decayed blaze.  
The original SW. and NW. bearing trees have been blown down and away from their original positions. Both of the trees are 50 ins. diam., with illegible scribe marks visible on the bark, and the remains of bearing trees mkd. by Godfrey:  
A fir stump, 25 ins. diam., bears N.8½°E., 90 lks. dist., with scribe marks T22S R4W S2 CS BT visible on an open blaze.  
A roothole, bears S.86°E., 95 lks. dist., with a down fir alongside, 26 ins. diam., no marks visible.  
A cedar, 34 ins. diam., bears S.30°W., 88 lks. dist., with healed blaze.  
and new bearing trees  
A fir, 12 ins. diam., bears N.82°E., 18½ lks. dist., mkd. T22S R4W S2 BT.  
A fir, 4 ins. diam., bears N.6°W., 29 lks. dist., mkd. X BT.

Dave Wellman, LS 2163 - For: Weyerhaeuser Co. - Erin Heatherstone - 3/10/2003 - C.S. File 65/45-10A&B

-----  
Found - 1¼" iron pipe with 1962 Douglas Co. Brass Cap 1' AGL  
26" Maple S.22°E., 30.2 ft. to spike set side center  
1954 BLM tag reads N.25°W., 71 lks. - rotten face  
34" Cedar, S.34°W., 60.4 ft. to spike set side center - closed face.  
continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

15" Fir, N.81°E., 8.7 ft. to spike set side center - closed face.  
4" Fir, N.14°W., 19.1 ft. to spike set side center, 1993 BLM tag reads S.6°E., 29.4 lks - "X" visible  
24" Fir stump, 1962 BLM tag reads S.8½°W., 59.3 ft. - rotting.

Other information -  
Fence post 1.0' East.  
Creek flowing N.82°W., 1' south of corner.