

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec Cor for 35 & 36; and 1 & 2, T23-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May, 28, 1851 (DCSO records Vol. 6 Page(s) 2265 and 2269)

Set post cor. of secs. 1, 2, 35 and 36, from which
A Fir 10" dia., bears N.55°W., 33 lks. dist.
A Redwood 11" dia., bears N.38°E., 11 lks. dist.
A Redwood 10" dia., bears S.10°E., 8 lks. dist.
A Maple 12" dia., bears S.40°W., 47 lks. dist.

Fd. and used in GL0 survey by Wm. P. Wright, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records, Vol. 4 Pages 1366-67)

O.F. Thiel - For: Thompson; Broady & Nelson - Nov. 1944 - C.S. File 61/5

Marks found on the NE. bearing tree, stump tree cut down. Set a Cedar post & mkd. a dead Cedar snag bears SE.

Survey by Glen McChesney (under Lester E. Calder) For: Weyerhaeuser Timber Co. - 2/29/1960 - C.S. File 51/87-1 (and C.S. File 53/1-47; C.S. File 53/105-34)

GL0 survey record, all evidence gone.
County Survey record, all evidence gone.
By careful retracement of the township line to the East and West, the original line trees were found and the corner was re-established at the prop. dist. between the following identified original line trees:
48" Fir, East 166 ft., 2 notches on E. and W. sides.
42" Fir stump, West 166 ft.
Referenced by McChesney (Weyerhaeuser method):
12" Red Cedar N.32°E., 22.0 ft.
50" Fir S.79°E., 39.9 ft.
32" Red Cedar stump, S.02°W., 31.4 ft.
66" Fir N.45°W., 28.6 ft.
(More information in file if needed)

Nov. 1965 - Cor. questioned by R. Tracy - Insufficient evidence. L.L. C.S. file 54/16-42A(?)

Douglas County Surveyors Office - Larry E. Monrean, Deputy - T.F. Franssen; S. Flause, crew - July 30, 1991 - C.S. File 64/17-2

Found - 12" R.Cedar, now a 12" stump 7 ft. high with
(Cont. Next Page)

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec Cor for 35 & 36; and 1 & 2, T23-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Weyerhaeuser nail and tag, bears N.35°E., (Rec. N.32°E) 22.0 ft.
50" Fir now a 38" stump 5 ft. high with Weyerhaeuser nail and tag, bears S.77°E., 41.6 ft. (Rec. S.79°E., 39.9 ft.)
32" Cedar stump 4 ft. high with Weyerhaeuser nail and tag, bears S.1°E., 32.2 ft. (Rec. S.2°W., 31.4 ft.)
66" Fir now a stump 6 ft. high with Weyerhaeuser nail and tag, bears N.43½°W., 28.6 ft. (Rec. N.45°W.)
Set a 1" x 36" Iron pipe with brass cap mkd:
Douglas County Surveyor
T 22 S R 4 W
S 35 | S 36
S 2 | S 1
T 23 S
1991

New Accessories;
4" Fir mkd. "X BT" on double blaze, bears N.77°E., 40.5 ft.
5" I.Cedar mkd. "X BT" on double blaze, bears S.3½°E., 43.6 ft.
7" Post, fence corner, fence runs South and West, bears S.68°W., 4.8 ft.
Monument set along northerly edge of power pole service road.

Fd. Brass cap, Oct. 1992 by D. Peel - M 115-77

Ken Hoffine - For: Lone Rock Timber Co. - 10/2000 - M 135-69

Found - DCS0 alum. cap 0.8 ft. below ground level.
34" D.Fir rotten stump bears S.78½°E., 42.6 ft. (Rec. S.77°E. 41.6 ft.)
68" D.Fir rotten stump bears N.43½°W. 30.9 ft. (Rec. N.43½°W., 26.6 ft.) rotten chopped out face.
No evidence of other BTs remain.
A 8" wooden fence post bears S.66°W., 4.8 ft.
Corner lies on SW slope in a power line R/W on West edge of power line service road.