

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; and 1 of T23-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May, 28, 1851 (DCSO records Vol. 6 Page(s) 2265 and 2269)

Set ¼ sec. post, from which
A Fir 17" dia., bears N.22°E., 26 lks. dist.
A Fir 28" dia., bears S.57½°W., 70 lks. dist.

Glen McChesney - (Under Lester E. Calder) For: Weyerhaeuser Timber Co. - 3/17/1960 - C.S. 51/87-1 & C.S. 53/1-54

GLO Survey record, post gone.
Found - 17" Fir N.22°E., 26 lks., now 38" Fir windfall, faces are up, filled with dirt and upper face rotted.
28" Fir S.57½°W., 70 lks., remains of roots of large Fir, S.58°W., 46.2 ft.
1" I.P. 6" out of ground for corner, good for dist. and bearing from GLO BTs.
Drove 1" x 30" alum. pipe beside the iron pipe.
Referenced by McChesney (plates and "W" nails only):
26" Fir N.71°W., 11.9 ft.
50" Fir S.75°W., 15.6 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, M. Stone and J. Layne, crew - Nov. 4, 1965 - C.S. File 54/16-37

Found - 1" Iron pipe and 1" alum. pipe as recorded.
Bearing trees all stumps, not scribed, "W" nails only.
New BTs -10" Hemlock N.61°W., 68.3 ft. mkd. ¼ S36 DCS BT.
7" Hemlock S.7°E., 58.7 ft. mkd. ¼ S1 DCS BT.
This corner is on Lane-Douglas County line.