

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 038050

PRIMARY CORNER DESCRIPTION SE Cor. Jesse Applegate DLC #38

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,  
dated Sept. 1856

-----  
Set Stone post 6 x 8 x 10", from which  
An Oak 15" dia., bears N.83°E., 245 lks.  
An Oak 30" dia., bears N.19°E., 143 lks.

Douglas Co. Surveyors Office - James Byron and Milo Godfrey  
-June 20, 1961 - C.S. File 49/59-34

-----  
Found - Orig. 30" now 48" B.Oak, N.19°E., 94.4 ft.,  
previously opened, shows good scribing "22S 5W  
BT"  
Orig. N.83°E., 161.7 ft., not found.  
Corner stone, not found.

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S R 5 W  
SE Corner DLC 38 \_\_\_\_\_ \

1961  
New BTs -30" B.Oak bears N.6°W., 23.4 ft. scribed SE Cl 38 CS  
BT.  
12" R.Fir bears S.29°E., 24.4 ft. scribed SE Cl 38  
CS BT.

Fd. OK, March 16, 1965, DCS0, B. Rogers, C.S. File 53/101

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 5/1/2001 - C.S. File 66/21-14

-----  
Found - 1961 DCS0 brass cap/iron pipe protrudes 13" above  
ground.  
30" now 40" dia., 20 ft. high Oak snag previously  
opened rotted blaze rec. N.19°E., 94.4 ft not  
measured. OBT  
30" now 39" dia., B.Oak with a fully healed double  
blaze bears N.6°W., 23.4 ft. 1961  
1961 SE BT now gone.

New - 16" dia., D.Fir double blazed & scribed "SE DLC 38  
CS BT" bears N.73½°E., 16.0 ft.  
9" dia., Cherry double blazed & scribed "SE DLC 38  
CS BT" bears N.70°W., 19.5 ft.  
13" dia., D.Fir double blazed & scribed "SE DLC 38  
CS BT" bears N.5½°E., 16.4 ft.  
Compass Decl. 17 3/4°E.

FD. Ok by K. Hoffine 4/2008 - M155-54