

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T22-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1383)

Set post cor. of secs. 25, 30, 31 and 36, from which
A W.Oak 15" dia., bears S.85°E., 349 lks. dist.
A Fir 15" dia., bears N.81°W., 404 lks. dist.
A Fir 6" dia., bears N.59°E., 241 lks. dist.
No tree near in sec. 36.

Survey by James Branch - For: U.S. National Bank - Nov. 25, 1992 - C.S. File 63/149-1C and Nov. 25, 1992

Set 5/8" x 30" rebar with yellow plastic cap mkd. Branch Eng. LS 1138., from which four 5/8" x 30" rebar with red plastic caps mkd. "Ref. Mon. LS1138" bearing:
N.60°W., 22.43 ft.
S.1°30'E., 18.96 ft.
S.89°30'E., 59.44 ft.
N.12°W.,, 65.60 ft.

Fd. OK, Aug. 1994, K. Hoffine, M 120-79
Fd. OK, Sept 1997, K. Hoffine, 1997-0128 A&B

DCSO-GIS Corner visitation - 11/29/2005 - Typed: 1/13/2011 - C.S. File 67/33-1

Monument - rebar Comment -5/8" IR W/YPC mkd. BRANCH EN

Fd. OK, Oct. 2007, R Betz, M154-40 (replaces M116-29)