

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1417)

Set ¼ sec. post, from which
A B.Oak 30" dia., bears N.18°W., 85 lks. dist.
A Fir 10" dia., bears S.50°W., 141 lks. dist.

O.F. Thiel - For: Harry Haines - Jan. 1931 - Field Book 116 Page 51

Set a Fir post and re-marked both old trees.
Corner stands on S. slope.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - April 12, 1965 - C.S. File 53/101-15

Corner not found.

Harvey M. Christensen, L.S. 2603 - For: Seneca Jones Timber Co. - Jan. 1995 - M 123-34

Found - 1" O.D. Iron Pipe (unknown Origin, held as found)
(.33' S, .45' W of calculated)
New BTs- 31" D.Fir S.45°W., 18.5', blazed & scribed "¼ S7 BT"
10" D.Fir S.64°E., 20.5', blazed & scribed "¼ S7 BT"
33" D.Fir N.84°E., 44.7', blazed & scribed "¼ S6 BT"
9' D.Fir, N.76°W., 33.3', blazed & scribed "¼ S6 BT"
Set - 5' steel post 1 ft. East.

DCSO-GIS Corner visitation - 10/31/2005 - Typed: 1/13/2011 - C.S. File 67/33-1

Monument - 3/4" ID iron pipe. Comment - OK

BLM Dependent resurvey by A. Bert Skeesick & Timothy J. Moore, Cadastral Surveyors & Robert H. Browning, Surveying Technician under Group No. 2133 surveyed April/May 2006 - (DCSO records Vol. 55 Page(s) 21714-5)

The ¼ sec. cor. of secs. 6 and 7, reestablished by person(s) unknown, there is no remaining evidence of the original corner, therefore this position is accepted as the corner, perpetuated by Christensen, in 1995, monumented with an iron pipe, 1" dia., firmly set, projecting 1" above ground, from which a reference by person(s) unknown
A fir, 37" dia., bears S.49°E., 34.4 ft., no scribe marks visible, with two Bureau of Land Management metal bearing tree signs attached, mkd. KC JB 1979. Cont.

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and bearing trees mkd. by Christensen

A fir, 36" dia., bears N.82 $\frac{3}{4}$ °E., 44.1 ft., with a healed blaze.

A fir, 11" dia., bears S.67°E., 20.5 ft., with a healed blaze.

A fir, 33" dia., bears S.40 $\frac{1}{2}$ °W., 18.9 ft., with a healed blaze.

A fir, 11" dia., bears N.79 $\frac{3}{4}$ °W., 33.3 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2 $\frac{1}{2}$ " dia., 26" in the ground, over the existing iron pipe, with brass cap mkd.

T22S R5W

$\frac{1}{4}$ $\frac{S\ 6}{S\ 7}$

2006

Bury a magnet in a white plastic case at the base of the stainless steel post.

Harvey M. Christensen, L.S. 2603 - For: Seneca Jones Timber Co. - May 2007 - M153-31

Found 2006 BLM BC (BLM resurvey not approved at this time) & 4 BTs from 1995. Also set 5/8"x30" rebar with 2.5" alum cap stamped "2007 LS 2603" for a property corner that bears S.89°27'29"W., 17.20 ft. No BTs set for property corner.