

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1388)

-----  
Set post cor. secs. 31 and 32, from which  
A B.Oak 6" dia., bears N.20°W., 173 lks. dist.  
A B.Oak 8" dia., bears N.19°E., 158 lks. dist.

-----  
From Vol. 2 Page 264 (by ?) (date ?) (Probably Thiel)

-----  
Reset corner post for sections 31 and 32 on standard parallel, from which  
R. Fir 8 ft. dia., bears N.75°20'E., 43 lks.  
R. Fir 12" dia., bears N.33°38'W., 1.48 lks. (?)  
Old BTs in evidence.

-----  
Reported by A.R. Evans, C.S. File 41/114 (date?)

-----  
Found rock set by Theil, (apparently) from O.B.T.

-----  
Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S. Bilow - March 4, 1958 - C.S. File 49/59-18

-----  
Found - 8" now 19" R.Fir N.75°20'E., 228.4 ft. I open upper scar and find good scribing "W S". This recorded as renewed, 1901, by ring count. It was scribed about 1928. Also the tree was 12" when scribed (Rec. 8")

Also find rotted base of Fir that checks bearings and distance for NW BT. Find upper section of old rotted and scribed stake on ground.

No trace of original BTs found.

Set Brass cap at cor. mkd: County Surveyors Office

S31|S32 T22S R5W  
S 6 T23S  
1958

New BTs -10" R.Fir bears N.11°W., 8.5 ft. scribed S31 T22S R5W CS BT.

20" R.Fir bears N.74°E., 47.5 ft. scribed S32 T22S R5W CS BT.

10" R.Fir bears S.44°E., 36.0 ft. scribed S6 T23S R5W CS BT.

Sketch in file showing location of brass cap.

-----  
Fd. OK, Feb. 1965, B.Rogers, C.S. File 53/101

-----  
Fd. OK, Sept. 1981, E. Bloom, M 88-75

-----  
Cor. Fd. & used in BLM resurvey by Jelley & Rogers, under Group #1119, surveyed 1982 (DCSO rec, Vol. 46 page 17670) -cont. next pg

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ken Hoffine, Lone Rock Timber Management - Crew: Daniel Saily and Ignacio Roman - 6/28/2019 - C.S. File 65/104-21

-----  
Found - 1958 Douglas Co. Surveyor's office brass cap (properly marked)  
20"x2' D.Fir stump bears N.73°E., 48.4 ft. (BLM record N.73°E., 48.18 ft (73 lks).) rotten face no tag.  
24" D.Fir bears N.13°W., 7.8 ft. (record N.11°W., 8.5 ft.) healed face and we tag

New - 12" D.Fir bears N.89°E., 23.6 ft. we scribe S 6 BT and tag  
5½ ft. galvanized U-Post 1.0 ft north.

Note - We ran a random closed loop traverse beginning at the corner of sections 31 & 32, traversing westerly to the East 1/16th corner of section 6, a Haines T-iron. We then took direct GPS observations of both monuments and rotated our survey to the GPS bearing, which is in the OCRS LDP zone Cottage Grove - Canyonville NAD 83, projection we then blazed, painted, flagged, posted with 5½ ft. U-Posts, and tagged true line. corner lies on north slope on north edge of small East West running bench, at corner of North and West running fence lines.