

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1410)

Set ¼ sec. post, from which
A B.Oak 15" dia., bears S.40°W., 79 lks. dist.
A Fir 40" dia., bears S.66°E., 184 lks. dist.

Survey by Wilford N. Haines - For: Rick McMullin - Aug. 1977
M 66-31

Found no trace of original corner. Area has been logged and burned.
Set 5/8" Rebar, from which
12" Fir N.53°W., 46.7 ft.
24" Fir N.74°E., 53.2 ft.

Survey by Harold Stockhoff LS #1663 - For: Milton W. Bedortha and Karl Hess - Aug. 1979 - C.S. File 58/208 and M 78-78

East ¼ corner sec. 31 was not found.
Set 5/8" Iron rod and remeasured dist. to existing BTs.
12" Fir N.56°45'W., 46.70 ft.
24" Fir N.74°19'E., 51.60 ft.

Fd. OK, April 1994, H.Pieske, M 120-4