

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1416)

-----  
Set ¼ sec. post, from which  
    A Fir 40" dia., bears S.85°E., 21 lks. dist.  
    A Fir 48" dia., bears S.38°W., 75 lks. dist.

O.F. Thiel - For: Frank Kent - Oct. 1899 - Vol. 2 Page 81 and Vol. 2 Page 261 and Field book 113 Page 37

-----  
One of the old bearing trees fallen and the marks burnt off the others but correspond in description.  
Set a Willow post from which  
    A Fir 12" dia., bears N.9°W., 83 lks. dist.  
    A Fir 50" dia., bears S.85°E., 21 lks. dist.  
In presence of Levi Kent, John Haskins, and James Haskins. SW original tree fallen down, letters still visible, the other BT remains, but marks burnt off.

Wm. C. Thomson - Feb. 1955 - C.S. File 41/344

-----  
Found - Fir 50" dia., S.85°E., 13.9 ft.  
        Fir stump, N.9°W., 54.8 ft.  
Set 5/8" Rod.  
Marked - Fir 14" dia., S.60°W., 24.9 ft.  
        Fir 18" dia., N.30°W., 27.0 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Darby, Mike Stone, Terry Connell, crew - Aug. 3, 1965 - C.S. File 53/101-44

-----  
Found - 5/8" Iron rod as recorded.  
        18" now 25" Fir N.30°W., 27.0 ft., good scar, alive and "S" scribe in wood. "W" nail in base of tree.  
        Orig. SE BT still alive but burned out.  
New BT - 7" D.Fir N.24°E., 31.5 ft. mkd. ¼ S8 CS BT.  
This corner lies on brushy, steep East slope approx. 250.0 ft. East of top of ridge.

Fd. Ok by H.Christensen, Jan. 1995 - M 123-34  
Found OK by L. Roberts, July 2000 - 2000-0051 A&B

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Dependent resurvey by A. Bert Skeesick & Timothy J. Moore, Cadastral Surveyors & Robert H. Browning, Surveying Technician under Group No. 2133 surveyed April/May 2006 - (DCSO records Vol. 55 Page(s) 21711-12)

-----  
The 1/4 sec. cor. of secs. 7 and 8, perpetuated by Thiel, in 1899; subsequently perpetuated by Thomson, in 1955; and further perpetuated by Tracy, et al, in 1965; monumented with a reinforcing bar, 5/8" dia., firmly set, projecting 3" above ground, from which the remains of an original bearing tree

A sawed, decayed fir stump, 77" dia., bears S.85°E., 17.1 ft., no marks visible. (Record, 13.9 ft.)

and a bearing tree mkd. by Thomson

A fir, 35" dia., bears N.30 1/2°W., 27.9 ft., with a healed blaze.

and a bearing tree mkd. by Tracy

A fir, 19" dia., bears N.24 1/2°E., 31.8 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" dia., 25" in the ground, over the existing reinforcing bar, with brass cap mkd.

T22S R5W

1/4

S 7 | S 8

2006

Bury a magnet in a white plastic case at the base of the stainless steel post.