

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1418)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 36" dia., bears S.38°W., 58 lks. dist. A Fir 8" dia., bears S.88°E., 30 lks. dist.</p>
<p>Survey by Donald Peel - For: Weyerhaeuser Corp. - Feb. 1992 - M 114-60</p> <p>-----</p> <p>Corner Report Only Found - Haines T-Iron and brass disk 29" Fir S.51½°W., 26.4 ft., closed face. 40" Fir stump, S.34½°W., 39.5 ft., wood rotted out but good face on bark. Center of root hole of blown down double Fir, East, 18.5 ft. No visible marks, but evidence of axe work where tree had chopped open previously.</p>
<p>Harvey M. Christensen, L.S. #2603 - For: Seneca Jones Timber Co. - Jan. 1995 - M 123-34</p> <p>-----</p> <p>Found - Haines T-Iron and brass disk 30" D.Fir S.52°W., 26.4 ft., closed healed face. 40" D.Fir stump, S.34°W., 39.7 ft., rotted out but good face on bark. New BTs- 9" D.Fir, S.02°E., 5.4', blazed & scribed "¼ S5 BT" 17" D.Fir, N.34°E, 34.6', blazed & scribed "¼ S5 BT" Set 5' Fiberglass post 1 ft. south.</p>
<p>DCSO-GIS Corner visitation - 10/26/2005 - Typed: 1/13/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - T-iron Comment - 1 live BT, 1 snag</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 4/26/2011 - C.S. File 67/33-36</p> <p>-----</p> <p>Found - 1"x1" Haines T iron with a 1" brass washer (mkd: MILFORD A. HAINES 235 SURVEY POINT DRAIN ORE.) at top is firmly and plumbly set protruding 1 ft. above ground. This monument is of unknown origin, it was first noted as fd in 1992 renewal. OBT: A fir 36" dia., now a rotted 40" dia., 3 ft. tall, fir stump with no remaining evidence of blazes or scribing; bears S.32°W., 39.5 ft. (orig. rec. S.38°W., 38.3 ft. - distance is a good face measurement - fd. distance agrees w/1992 rec.) Cont.</p>

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias	Description

OBT: A fir 8" dia., now a 20+" dia., rotted, fallen on face and out of position fir with possible healed blaze. The root-hole of this tree bears N.85°E., 19.8 ft. (rec. S.88°E., 19.8)

1992: A BT described as fd and probably mkd by Haines in unrecorded renewal. A 29" fir, now a 35" DBH D.Fir with a fully healed single blaze; bears S.48°W., 26.4 ft. (rec. S.51½°W., 26.4 ft.)

1995: A 9" D.Fir now a dead 9" DBH D.Fir with a slightly healed single blaze with the scribing "¼ S5 BT" visible; bears S.5°E., 5.9 ft. (Rec. S.2°E., 5.4')

1995: A 17" D.Fir now a fallen & rotted 17" DBH D.Fir with a partially healed single blaze showing the scribing "¼ S5 BT" The root-hole of this tree bears N.32°E., 34.6 ft. (Rec. N.34°E., 34.6')

Found Monument is in good stable condition.

New - A 15" DBH D.Fir scribed "¼ S5 CS" "BT" on a double blaze; bears N.47½°E., 11.5 ft.

A 23" DBH Maple scribed "¼ S5 CS" "BT" on a double blaze; bears S.62°E., 23.3 ft.

A 12" DBH D.Fir scribed "¼ S6 CS" "BT" on a double blaze; bears N.13½°W., 10.5 ft.

Note - Monument is approx. 2 ft. south from a down East-West fenceline. Monument is on a steep westerly slope in an old second growth fir forest approx. 100 ft. north from edge of a large newer clear-cut with cut boundaries running south and NW.

Compass decl. 15¾°E.