

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1404)

-----  
Set ¼ sec. post, from which  
    A Maple 5" dia., bears N.85°W., 11 lks. dist.  
    A Fir 36" dia., bears N.14°E., 36 lks. dist.

O. F. Thiel - Wit: Ernest and Herman Thiel - June 27, 1900 - Vol. 2 Page 262

-----  
The SW BT has been cut down but the BT is plain on stump and corresponding to description in original field notes. The NW tree is entirely gone. Set a Maple post, from which  
    A Maple 5" dia., bears S.36°W., 62 lks. dist.  
    A Maple 7" dia., bears S.69°E., 81 lks. dist.

Wilford N. Haines - For: Woolley Logging Co. - Aug. 15, 1967 - Haines records, H En. 3

-----  
Set 5/8" steel rod.

Douglas Co. Surveyors Office - L.E. Monrean and P.L. Earle - Dec. 30, 1975 - C.S. File 57/39-50

-----  
Found - A 5/8" dia. Iron rod, from which  
    An 8" dia. D.Fir bears N.59°E., 12.9 ft. Tree is blazed and scribed "¼S 33 BT". (Not of record)  
    A 25" dia. D.Fir bears N.60½°W., 27.6 ft. Tree has a good blaze, I open and find scribing "¼ S32 BT". (Not of record.) (Possible Haines, see Field book, H-110)

No original or record evidence found. The unrecorded evidence found appears to be approx. 8 years old.

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed Oct. 1982/Feb. 1984 (DCSO records Vol. 46 Page(s) 17682)

-----  
The ¼ sec. cor., restored by person(s) unknown, recorded by Eugene Bloom in 1981, (See M 79-79) and is accepted as the best available evidence of the position of the original corner, monumented with an iron rod, 5/8" dia., firmly set, projecting 8" above ground, from which bearing trees mkd. by person(s) unknown

    A Fir 10" dia., bears N.49°E., 19 lks. dist., with scribe marks ¼ S33 BT visible on opened double blaze.

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir 29" dia., bears N.60½°W., 43 lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 5 W  
1/4  
S 32 | S 33  
1983

Reset iron rod alongside alum. post.

The corner is located in ravine, drains N.60°E.

(Possible record for above "unknown" is Haines Field book, H-110)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 12/1/2005 - C.S. File 67/13-16

Found - 3" alum cap on alum post marked (properly) firmly set. AC/AP projects 8" above ground. 5/8" iron rod alongside.

29" Fir now 29"x5 ft. tall stump bears N.60½°W., 28.4 ft. (agrees w/1983 BLM rec) Probably Haines BT from 1967.

10" Fir now down & rotted, fd near record position (BLM rec. N.49°E., 12.5' DCSO rec. N.59°E., 12.9'

New - 8" D.Fir scribed "¼ S32 CS BT" bears N.13½°W. 6.2 ft  
6" D.Fir, pistol butt, mkd: "X CS BT" bears N.69°E., 16.0 ft.

Note - No suitable trees within range in SE & SW quadrants.  
Corner lies at the bottom of a steep ravine.  
Compass decl. 16¾°E.