

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1409)

Set post cor. of secs. 4, 5, 8 and 9, from which
A W.Oak 18" dia., bears N.25°W., 224 lks. dist.
A W.Oak 18" dia., bears S.30°E., 459 lks. dist.
Erected stone mound as per instructions

O.F. Thiel - For: Floyd O. Craig - Aug. 1927 - Field Book 116 Page 23

At SW cor. of 4, remarked NW tree. Cor. at place by C.S.

Eppstein and Bowker - For: J.O. Craig - Oct. 14, 1926 - C.S. File 3/60

Found - W.Oak N.25°W., 147.8 ft. Old BT, marks visible, center decayed, blaze not grown over.
Set 3" x 3" x 3 ft. Oak stake.
Remarked-20" Fir S.40°E., 8.4 ft.
20" Fir S.63½°W., 26.9 ft.
20" Fir N.40°W., 32.3 ft.
12" Fir N.18°E., 24.8 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putman - Aug. 19., 1959 - C.S. 49/59-33

Found - All four of Eppstein's BTs:
20" now 24" R.Fir S.40°E., 8.4 ft. previously opened, shows good scribing "S 2"
SW and NW BTs, now stumps
NE BT, now down, all check bearings and distances.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 5 W
S 5 | S 6
S 8 | S 9
1959
New BTs -24" R.Fir bears S.8°W., 26.3 ft. scribed S8 T22S R5W CS BT.
6" W.Oak bears N.4°W., 102.6 ft. scribed S5 T22S R5W CS BT.
11" R.Fir bears N.26°E., 49.8 ft. scribed S4 T22S R5W CS BT.
Corner is on large sandstone. Top of brass cap leans West but is on corner.

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec Cor for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - March 1965 - C.S. File 53/101-34

Found - 6" Oak now 8" N.4°W., 102.6 ft., shows good scar.
11" Fir now 13" N.26°E., 49.8 ft. shows good scar.
24" R.Fir, down, S.8°W., 26.3 ft.

(Cont. Next Page)

24" R.Fir, broken, S.40°E., 8.4 ft., shows remnants of scribing.

Corner lands on sandstone as described by Byron, but brass cap is missing. Set 3/4" Iron rod.

New BTs -18" D.Fir S.31°E., 55.0 ft. mkd. T22S R5W S9 CS BT.

16" D.Fir S.39°W., 103.0 ft. mkd. T22S R5W S8 CS BT.

Corner is approx. 30 ft. North of fence corner.

Survey by Donald Peel, L.S. #752 - For: Weyerhaeuser - Feb. 1992 - M 114-60

Corner Report Only

Found - 3/4" rebar.

24" Fir N.24°E., 49.1 ft., closed face.

12" Fir stump S.30¼°E., 54.5 ft., visible scribe.

22" Fir S.41¼°W., 103.0 ft., closed face.

10" Oak N.5°W., 102.1 ft., closed face.

22" rotted Fir stump N.41°W., 32.8 ft.

Found OK by D. Baker, Feb. 1996 - M124-13

Found OK by L. Roberts, July 2000 - 2000-0051 A&B

Found OK by D. Edwards, Aug. 2002 - 2002-0035

Fd. OK 8/2022 - M Heimburger 2022-0039B