

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; and 33 of T21-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 792)

-----  
Set ¼ sec. post, from which  
A W.Oak 24" dia., bears N.51°W., 229 lks. dist.  
A Fir 30" dia., bears S.55°W., 405 lks. dist.

Survey by J.W. Cole, County Surveyor - For: W.C. Sagaberd and J. Grimm - Jan. 1924 - Vol. 3 Page 176; Field Book 52 Pg. 21; and C.S. File 16/8

-----  
I renewed corner from stumps of original bearing trees which checked for position but bore no marks as they were badly decayed:  
Large W.Oak, N.51°W., 229 lks.  
Fir, S.55°W., 405 lks.  
Fence corner 15 ft. South and 10 ft. West.  
I set an Iron pipe 1" x 36", from which I mark:  
A W.Oak 10" dia., S.50°50'W., 147.9 ft.  
A Fir 30" dia., N.47°W., 66.8 ft.

Arthur Boyer - Jan. 10, 1938 - C.S. File 16/8

-----  
Renewed markings on 30" Fir, N.47°W., 66.8 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Wm. Stoffel and Mike Stone, crew - Dec. 1, 1964 - C.S. 49/68-49

-----  
Found - 3/4" Iron pipe.  
Fir stump, N.47°W., 66.8 ft., bark scribing visible "33 21/5"  
16" W.Oak S.51°W., 147.9 ft., shows very plain scar. No trace of original BTs.  
20" Fir S.66°W., 30.0 ft., recently scribed. No Record.  
New BT - 38" D.Fir N.28°W., 20.0 ft. mkd: ¼ S33 CS BT. (This tree in fence line, N and S.)  
DID NOT SET BRASS CAP.

BLM sec. subd. by Wayne L. Rogers, Cadastral Surveyor, under Group #1059, surveyed April/Dec. 1981 (DCSO records Vol. 45 Page(s) 17326-27)

-----  
The ¼ sec. cor., perpetuated and recorded by Cole in 1924, from original evidence no longer in existence, and further perpetuated and recorded by Godfrey in 1964, monumented with an iron pipe, 3/4" dia., firmly set, projecting 2" above ground, from which the remains of bearing trees mkd. by Cole:

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33 of T21-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A twin Oak 34" dia., bears S.47 3/4°W., 226 lks. dist., with healed blaze.

A Fir stump 27" dia., bears N.54 1/4°W., 110 lks. dist., with healed blaze.

and a bearing tree mkd. by person(s) unknown and recorded by Godfrey:

A Fir 24" dia., bears S.65°W., 46 lks. dist., with a healed double blaze.

and a bearing tree mkd. by Godfrey:

A Fir 42" dia., bears N.30 1/2°W., 30 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 21 S R 5 W

1/4 S 33  
S 4

T 22 S R 5 W

1981

From this point, DCSO Horizontal control station "HEATHER", bears N.73°25'E., 27.09 chs. dist., monumented with a concrete post, 8" square, firmly set, the top flush with the surface of the ground, with brass tablet 2 1/2" dia., set in top, mkd. HEATHER 1979.

From this same point, the intersection of wire fences, extending N. and S.80°E., bears S.70°E., 0.14 chs. dist.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Feb. 2, 1992 - C.S. File 64/23-6

Found - 3 1/4" dia. 1981 BLM brass cap on a 2 1/2" O.D. iron pipe, protruding 1" above ground.

3/4" I.P. from 1924, not seen.

30" now 28" dia., 5 ft. high rotted D.Fir stump with bark scribing visible "31/5" bears N.47°W., 67.8 ft. (Rec. N.47°W., 66.8 ft., dist. possible face measurement, 1924) (1981 BLM record brg. & dist. to wrong stump)

10" now 37" dia. W.Oak with a fully healed single blaze, bears S.47 3/4°W., 149.2 ft. (agrees w/rec, 1924)

20" now 29" dia., D.Fir with a fully healed single blaze bears S.66°W., 30.0 ft. (agrees w/rec)

38" now 38" dia., 4 ft. high D.Fir stump with a fully healed single blaze bears N.28°W., 20.0 ft. (agrees w/rec)

(Cont. Next Page)

