

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1399)

Set ¼ sec. post, from which
A B.Oak 7" dia., bears N.15°E., 16 lks. dist.
A B.Oak 24" dia., bears S.43°W., 16 lks. dist.

O.F. Thiel - June 1900 - Vol. 2 Page 262 - Present: Ernest and Herman Thiel

Set a Fir post, from which
A W.Oak 12" dia., bears N.45°E., 75 lks. dist.
A B.Oak 32" dia., bears S.43°W., 16 lks. dist.
The NE BT having been cut down for fence but by cutting in stump, I find original marks. SW BT being badly decayed where it was originally marked, but the tree being vigorous, I remarked same.

Douglas Co. Surveyors Office - Bruce R. Rogers, Deputy - Stoffel and Stone, crew - Jan. 1965 - C.S. File 53/101-26

Found - Old wood stake and 1" plugged I.Pipe at corner in E-W fence.
24" B.Oak now 33", orig. BT, S.43°W., 10.6 ft., shows good scar.
12" W.Oak now 15", chopped out, good scribing "BT", N.45°E., 49.9 ft.
New BT - 15" D.Fir S.22°W., 27.4 ft. mkd. ¼ S33 CS BT.

BLM sec. subd. by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed Oct. 1982/Feb. 1984 (DCSO records Vol. 46 Page(s) 17687-88)

The ¼ sec. cor., perpetuated and recorded by Thiel in 1900, and further perpetuated and recorded by Rogers in 1965, monumented with an iron pipe 1½" dia., firmly set, projecting 4" above ground, from which the remains of an original BT:
A B.Oak stump 36" dia., bears S.43°W., 16 lks., no marks visible.
and a bearing tree recorded by Thiel
A W.Oak 20" dia., bears N.44°E., 78 lks. no marks visible.
and the remains of a bearing tree mkd. by Rogers
A Fir stump 21" dia., bears S.22°W., 41½ lks., with healed blaze.
At the corner point
Set an alum. post, 28" long, 2½" dia., 24" in the ground, with alum. cap mkd: (Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>T 22 S R 5 W 1/4 S 33 S 34 1983</p>
<p>from which new bearing trees A Fir 9" dia., bears N.65¼°E., 21 lks., mkd. ¼ S34 BT. A Fir 6" dia., bears S.30¼°W., 4½ lks., mkd. ¼ S33 BT.</p>
<p>Fd. OK, Feb. 1994, M 118-66 Fd. OK, Jan. 2000 by M. Heimbürger - M134-21 Fd. OK, Aug. 2003, J. Estabrook, M137-66</p>
<p>DCSO-GIS Corner visitation - 12/8/2005 - Typed: 1/18/2011 - C.S. File 67/33-1 ----- Monument - 3" alum. cap Comment - 3 live BTs</p>
<p>Fd. Ok, June 2006 D. Edwards M150-66</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flauser - Mike Koch - 7/22/2013 - C.S. File 67/38-45 ----- Found - 1983 BLM 3¼" dia., alum. cap (properly mkd) on a 2½" I.D. alum. pipe is protruding 6" above ground. A metal plugged 1½" O.D. iron pipe is set protruding 2" above ground along the SE edge of the BLM BC/IP. Origin unknown 1965 renewal. No evidence of NE orig. BT. Possible root-hole of SE OBT Fd near record bearing & dist. A W.Oak 12" dia., now a 21" dia., W.Oak with a previously opened but now completely rotted away blaze; bears N.41¼°E., 51.5 ft. (rec. N.45°E., 49.5 ft. meas. distance agrees w/BLM record) 1900 A 15" D.Fir now an 18" dia, 2 ft. tall rotted D.Fir stump with no blaze or scribe evidence fd; bears S.22°W., 27.4 ft. (as per rec.) 1965 A fir 9" dia., now a 14" dia., D.Fir with a fully healed single blaze; bears N.66¼°E., 13.9 ft. (Rec. N.65¼°E., 13.9 ft.) 1982-84 A fir 6" dia., now an 18" dia., D.Fir with a fully healed single blaze; bears S.28½°W., 3.0 ft. (rec. S.30¼°W., 3.0 ft.) 1982-84 New - A 20" dia., D.Fir scribed "¼ S33 CS" "BT" on a double blaze; bears N.22¼°W., 16.6 ft. Note - Monument is 2 ft south of an E-W wire fence on a broad flat shelf in an old reprod fir forest. Compass decl. 15½°E.</p>