

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1403)

Set ¼ sec. post, from which
 A B.Oak 14" dia., bears S.40°W., 36 lks. dist.
 A B.Oak 16" dia., bears N.55°W., 116 lks. dist.

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952
RM 1-40

Post and iron pipe, set by single proportion.
Original BTs destroyed.
New BTs -10" Fir N.32½°E., 23.45 ft. mkd. ¼ S RP BT.
 24" Fir S.12°W., 40.25 ft. mkd. ¼ S RP BT.

(Per C.S. File 53/101, Sec. cor. for 10, 11, 14 and 15, not properly set, therefore, ¼ not right.)

Donald Peel, LS #752 - For: Weyerhaeuser Company - Jan. 1988
M 105-54

Found - 1" Iron pipe.
 16" Fir N.34°E., 23.9 ft., closed face.
 BT at S.12°W., now blown down.
New BT - 19" Fir S.44½°E., 44.6 ft. scribed ¼ S15 BT.

Ronald Geisler, LS #1988 - For: Champion International Corp.
Feb. 1991 - C.S. File 63/113 and M 111-54

Found - 1 3/8" O.D. Iron pipe with wood stake and nail in top.
 21" Fir bears S.46°E., 44.6 ft. (Rec. S.44½°E., 44.6 ft.)
 17" Fir bears N.32½°E., 23.9 ft. (Rec. 23.45 ft.)
New BT - 9" Fir bears S.72°W., 10.7 ft. scribed ¼ S15 BT.
No BTs available in the NW quadrant.

DCSO-GIS Corner visitation - 10/11/2005 - Typed: 1/18/2011 -
C.S. File 67/33-1

Monument - 1" ID iron pipe. Comment - OK, 3 standing BTs