

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T21-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 791-2)

Set ¼ sec. post, from which
A Fir 50" dia., bears N.8°E., 72 lks. dist.
A Fir 18" dia., bears S.62°E., 118 lks. dist.

Survey by David H. Wellman - For: Weyerhaeuser Co. - Oct. 28, 1988 - C.S. File 63/85-3 and M 107-26

Found - 72" rotted Fir stump with axe marks, N.8°E., 72 lks.
Set 1" x 36" Iron pipe with yellow plastic cap inscribed "Weyer Co".
New BTs -14" Fir N.38°W., 28.9 ft. to "W" nail and tag scribed "¼ S34 BT"
15" Fir S.2°W., 42.8 ft. to "W" nail and tag scribed "¼ S3 BT".
14" Fir S.70°W., 60.8 ft. to "W" nail and tag scribed "¼ S3 BT".

Fd. OK, Sept. 1993, D. Baker, M 118-10
Fd. OK, Oct. 1995, D.Baker, M 119-77

Daniel Baker for Weyerhaeuser Co. Feb. 1996 - M124-12

1/4 Corner for Section 34; & Section 3 T.22-5
Found - 1" I.P w/yellow cap marked "Weyer Co", 1988; M107-26
72" Fir stump, N.7½°E., 47.5 ft. - axe work visible record: N.8°E., 72 lks. 1855 G.L.O.
21" Fir, S.1°W., 42.8 ft. to "W" Nail - scribe visible record: S.2°W., 42.8 ft. to "W" Nail - 1988 Weyerhaeuser
20" Fir, S.68½°W., 60.8 ft. to "W" Nail - scribe visible record: S.70°W., 60.8 ft. to "W" Nail - 1988 Weyerhaeuser
20" Fir, N.39 ¾°W., 28.9 ft. to "W" Nail - scribe visible record: N.38°W., 28.9 ft. to "W" Nail - 1988 Weyerhaeuser

New Accessories -
6 ft. metal fence post bears south 1 ft.

DCSO-GIS Corner visitation - 10/18/2005 - Typed: 1/18/2011 - C.S. File 67/33-1

Monument - 1" ID Iron rod. Comment - 1 live BT.

continued next page

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - 4/19/2011 - C.S. File 67/33-35

Found - 1988 1" I.D. iron pipe with a yellow plastic cap (marked WEYER.CO. and oriented south) is firmly set protruding 16" above ground.

OBT: A fir 50" dia., now a very rotted 72" dia., 1 ft. tall fir stump with no blaze or scribing remaining; bears N.8°E., 47.5 ft. (as per rec)

1988: A 14" fir now a 22" dia., fallen to side fir with a partially healed double blaze (no visible scribing) ("W" nail not seen) The root-hole of this tree bears N.39¾°W., 28.9 ft. (This B & D agree with 1996 renewal, 1988 rec. N.38°W., 28.9 ft.)

1988: 15" fir now a fallen on face & out of position 21" fir with a partially healed double blaze showing illegible scribing ("W" nail not seen) The root-hole of this tree bears S.2°W., 44.0 ft. (Rec. S.2°W., 42.8 ft. to "W" nail)

1988: 14" fir now a 26" DBH D.Fir with a fully healed double blaze; bears S.72½°W., 62.0 ft. (rec. S.70°W., 60.8 ft. to "W" nail (nail not seen))

1996: A 6 ft. metal fence post now a metal fence post protruding 4 ft. above ground; bears South 1 ft. (as per rec)

Monument in good condition.

New - A 7" DBH Maple double blazed & scribed "X" "CS BT" on a high-low blaze; bears N.75°E., 19.4 ft.

A 13" DBH maple scribed "¼ S3 CS" "BT" on a double blaze; bears S.3°W., 3.9 ft.

A 5" DBH D.Fir double blazed & scribed "X" "CS BT" on a high-low blaze; bears N.59°W., 8.8 ft.

Note - Monument is on moderate NE slope 60 ft. west from a seasonal stream in a draw running NW. Monument is at NW corner of old growth timber stand. Newer clear-cuts occupy the other quadrants.

Compass decl. 15¾°E.