

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1398)

-----  
Set ¼ sec. post, from which  
A B.Oak 20" dia., bears N.53°E., 56 lks. dist.  
A Fir 40" dia., bears N.15°W., 50 lks. dist.

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952  
RM 1 - 40

-----  
Post and iron pipe.  
B.Oak 20" N.53°E., 56 lks. (destroyed)  
Fir 40" N.15°W., 50 lks. (stump, rescribed)

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - Jan. 29, 1958 - C.S. File 49/59

-----  
Found - 3/4" Iron pipe and post.  
56" Fir N.15°W., 33.8 ft., new scribed ¼S BT.  
I can find no trace of original BTs.

Bruce A. Shaner - For: U.S. BLM - Sept. 18, 1972 - M 49-12

-----  
Found - 3/4" Iron pipe 16" above ground.  
40" Orig. D.Fir, stump, face and scribing visible, bears N.15°W., 33.0 ft.  
32" D.Fir, face visible, bears N.86°E., 47.8 ft.  
22" D.Fir, face visible, bears S.86½°E., 45.1 ft.  
Set Brass cap mkd: T22S R5W WM S15 S14 ¼S 1972.

Fd. OK, Jan. 1988, D.Peel, M 105-54

Daniel Baker - For: Weyerhaeuser Co. - Aug. 1994 - M 119-39

-----  
Found - 2½" BLM brass cap, 1972, buried and out of position due to logging. Replaced by existing BT and transit note data from previous work at this corner.  
38" Fir stump, N.86¼°E., 47.0 ft., closed face.  
20" Fir stump, S.87¼°E., 44.5 ft., closed face.  
52" Fir stump, N.14 3/4°W., 34.3 ft., scribing visible. (Rec. N.15°W., 50 lks., 1855 OBT.)  
New Accessories:  
30" Fir stump S.10°W., 37.2 ft.  
6 ft. metal fence post 1 ft. East.