

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1393)

Set ¼ sec. post, from which
A Fir 10" dia., bears S.39°E., 28 lks. dist.
A Fir 24" dia., bears S.67°W., 29 lks. dist.

O.F. Thiel - For: J.M. Stock - Nov. 9, 1900 - Field Book 113 Page 95

¼ sec. cor. bet. secs. 13 & 14, SE bearing tree fallen, and SW tree cut down but old marks found on log. Set a Cedar post.

B.H. McGillicuddy - March 1955 - C.S. File 42/33

Established corner half way between section corners.
Set 1/2" x 30" Iron pipe, from which
28" Apple tree, N.41°41'E., 143.43 ft., nail in tree.
24" Oak, S.23°35'W., 189.45 ft., nail in tree.
Light pole, N.9°18'W., 347.19 ft.
Light pole, S.31°03'E., (?).

Search for corners shown as found, did not substantiate the above work. See C.S. File 49/59

Survey by Donald Peel, LS #753 - For: Weyerhaeuser Co. - Dec. 1987 - M 105-27

Found - Iron bolt with 1" head. Steel fence post southerly 1 ft. ±.
Sawed off base of power pole, N.8°52'W., 347.2 ft.
New B.O.-New power pole bears S.30°38'E., (?).

Found OK by D.Baker, Feb. 1999 - M129-46
Found OK by D. Edwards, Dec. 2003 - M144-6

DCSO-GIS Corner visitation - 10/19/2005 - Typed: 1/19/2011 - C.S. File 67/33-1

Monument - Iron bolt Comment - (needs) rehab

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Jason Martin - July 20, 2011 - C.S. File 67/33-41

Found - (1987) An iron bolt with a 1" sq. head is firmly set with top flush with ground. No evidence of 1955 1/2" iron pipe is found.

No evidence of OBTs found.

(1955) Possible evidence of one bearing object found; A light pole now a 10 1/2" DBH power pole tagged "5B-42" and with the earliest date tag of 1996; bears S.30 1/2°E., 152.8 ft. (Bearing agrees w/1987 renewal, 1955 & 1987 renewals did not record a distance)

A new power pole appears to replace NW light pole from 1955 renewal (sawed off base in 1987 renewal) but no evidence of the 1955 light pole remains.

Monument- Monument is stable we do not disturb. Monument is in mowed field we do not re-establish witness sign.

New BTs- A 5 1/2 x 5 1/2" sq. pressure-treated wood SE corner post of a small 40x48 ft hay barn; bears N.3°E., 248.0 ft
A 20" DBH maple scribed "1/4 S14 CS" "BT" on a double blaze; bears S.14 3/4°W., 140.5 ft.

A 9 1/2" DBH power pole tagged "5B" (over) 43 (over) 1" with the earliest date of 1996; bears N.9 1/4°W., 348.1 ft.

Note - Monument is in open gently undulating hay field and is 200+ ft. north of Elk Creek and 350 ft. south of Boswell Road.

Compass decl. 15 3/4°E.