

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1390)

-----  
Set ¼ sec. post, from which  
A Cedar 12" dia., bears N.42°W., 52 lks. dist.  
A Fir 40" dia., bears S.57½°E., 72 lks. dist.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 812 Surveyed Aug./Sept. 1973 (DCSO records Vol. 36 Page(s) 15059)

-----  
The ¼ sec. cor., determined at record bearing from the original bearing trees:

A Cedar 34" dia., bears N.42°W., 52 lks. dist., with healed blaze.

A Fir 54" dia., bears S.57½°E., 79 lks. dist., with scribe marks ¼ S visible on weathered bark blaze. (Rec. 72 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4  $\frac{S\ 25}{S\ 36}$   
T 22 S R 5 W  
1973

Referenced out by Wilford Haines for road construction, Dec. 4, 1980 - C.S. File 59/30

Wilford N. Haines - March 10, 1981 - C.S. File 58/229-42

-----  
Found - BLM brass cap leaning against NW BT.  
34" I.Cedar, orig., bears N.42°W., 52 lks.  
5/8" iron rod bears N.42°W., 11.89 ft.

Drove 5/8" x 40" rebar at orig. point for ¼ corner. This point in road about one foot from bank. Set BLM brass cap stamped W.P. 17 ft., bearing N.59°49'E., 17 ft. from 5/8" rebar.

New BT - 26" D.Fir bears N.59°49'E., 38 ft.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Teresa Buley, witness - Dec. 1, 1981 - C.S. File 61/29-39

-----  
(Referenced notes from C.S. File 59/30 now attached to renewal in C.S. File 61/29)

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Found - 5/8" x 40" I.R. in North edge of road, buried by a small slide. (1/4 corner)

1973 BLM brass cap reset by Haines as witness cor, bears N.60°E., 17.0 ft. from iron rod, with Haines added marks "WT<--17/FT"

5/8" x 40" I.R. set by Haines bears N.46°W., 12.0 ft. from the 5/8" I.Rod ¼ corner.

(These found BTs bear from 5/8" I.Rod 1/4 corner):

34" Cedar bears N.46°W., 34.3 ft. (Rec. N.42°W.) alive with good scar and nail.

54" Fir, now stump buried by road construction, bears S.56°E., 52.1 ft. (Rec. S.57½°E.)

26" Fir now 18", and alive with scribed "¼ S25 239 BT" visible in unhealed blaze, bears N.60°E., 38.0 ft.

At the exact location of 5/8" x 40" I.R. in road shoulder, I SET a 1" x 22" I.P. with brass cap stamped:

Douglas Co Surveyor

T 22 S R 5 W

1/4 S 25

S 36

1981

I put metal fence post with a survey marker sign 1.0 ft. North of corner.

New BTs -13" Fir scribed "¼ S25 CS BT" in double blaze bears N.55°W., 13.7 ft.

17" Fir scribed "¼ S25 CS BT" in double blaze bears N.84°E., 61.1 ft. This same 17" Fir bears S.87°E., 46.8 ft. from the 1973 BLM brass cap, which is now a witness corner.

C.S. File contains sketch and reference notes.

Fd. evidence under slide, Oct. 1992, K.Hoffine, M 116-2

DCSO-GIS Corner visitation - 1/10/2006 - Typed: 1/19/2011 - C.S. File 67/33-1

-----  
Monument - IP/BC buried under stump/slide.

Comment - 2 wit. mons, 3 stumps.