

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18 of T22-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1335)

Set ¼ sec. post, from which
A Fir 4" dia., bears N.50°E., 226 lks. dist.
A Fir 40" dia., bears S.88½°W., 130 lks. dist.

Survey by Donald Peel, LS #752 - For: Weyerhaeuser Co. - Dec. 1987 - M 105-27

Set 2" x 42" Iron pipe with brass cap mkd: "T22S R5W R4W ¼ S13 S18 PLS 752 1987".
New BTs -14" Fir S.52°E., 16.9 ft. scribed ¼ S18 BT.
20" Fir S.47°W., 23.2 ft. scribed ¼ S13 BT.

Fd. B.C., July 1992, R.Dolan, M 115-37

Fd. OK, Feb. 1999 by D.Baker - M129-46

David Edwards - For: Nancy Benzel - 12/2003 - M 144-6

The brass capped iron pipe which was monumenting the east ¼ corner has been hit by a bulldozer & is badly damaged & bent over. I set my pin & cap at record position from the 2 BTs noted on M129-46 (17" Fir, S.52°E., 16.8' & 21" Fir, S.47°W., 23.2')
Set - 5/8"x30" steel rebar w/red plastic cap mkd: D.A. EDWARDS-LS 2339

Fd. BC bent by N. Hibbs, 8/2008 - M156-42