

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec Cor for 12 & 13; 7 & 18, T22-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1335)

Set post, cor. of secs. 7, 12, 13 and 18, from which
A Fir 30" dia., bears S.44°W., 95 lks. dist.
A Fir 40" dia., bears S.38°E., 105 lks. dist.
A Fir 30" dia., bears N.14°E., 43 lks. dist.
A Maple 8" dia., bears N.37½°W., 32 lks. dist.

O.F. Thiel - For: Jake Wilson and Davis - March 1945 - Field Book 118 Page 64

Fd. old post, marked Cedar, 12", S.40°E., .08 (?)

Post & 4 BTs fd. Orig.cor. McGillicuddy - 4/1952 - RM1-40

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow - Jan. 27, 1958 - C.S. File 49/59-11

Found - Wooden stake at corner.
30" Fir snag S.44°W., 62.7 ft., showing old bark scribing. The figure "13" was all that was legible.
40" Fir, uprooted and down, S.28° or S.30°E. (instead of S.38°E.), 69.3 ft., old scribing visible "S 18 T22S R4W"
N.37½°W., 21.1 ft. was remains of old Maple stump with live Maple tree growing out of one side.
No evidence of NE BT could be found.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S
R5W $\frac{S\ 12}{S\ 13}$ | $\frac{S\ 7}{S\ 18}$ R4W
1958

New BTs -5" Fir S.45°W., 8.2 ft. scribed "S13 CS BT"
12" Yew N.40°W., 16.8 ft. scribed T22S R5W S12 CS BT
18" R.Cedar N.72°E. 8.5 ft. scribed T22S R4W S7 CSBT
16" R.Cedar S.48°E., 5.2 ft. fd scribing 5 to 10 yrs old on this tree "T22S R4W S18 BT". I added "CS"
The Maple growing out of stump of old Maple BT was also scribed 5 to 10 years ago. Scar was mostly covered but could see scribe marks, bearing N.40°W., 21.1 ft.

Fd. OK, Dec. 1987, D.Peel, M 105-27
Fd. OK, Feb. 1999 by D.Baker - M129-46

continued next page

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec Cor for 12 & 13; 7 & 18, T22-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2002, surveyed Jan/March 2002- (DCS0 rec. Vol. 54 Page(s) 20811-2)

The cor. of secs. 7, 12, 13, & 18, on the W. bdy. of the Tp., recovered by McGillicuddy, in 1952, perpetuated by Byron, in 1958, recovered by Peel, in 1987, & recovered by Baker, in 1999, monumented with an iron post, 1½" dia., firmly set, projecting 15" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

A fir snag, 21" dia., bears S.44°W., 62.7 ft., with no marks visible.

A maple stump, 20" dia., bears N.41¾°W., 21.5 ft., with healed blaze. (Record N.37½°W., 21.1 ft.)
and remains of bearing trees mkd. by Byron

A cedar, 30" dia., bears N.72½°E., 8.2 ft., with healed blaze.

A sawed cedar stump, 38" dia., bears S.50¼°E., 5.2 ft., with healed blaze.

A fir snag, 7" dia., bears S.44½°W., 8.0 ft., with healed blaze.

A yew, 12" dia., bears N.38°W., 16.9 ft., with scribe marks 22S R5W 12 CS BT visible on partially healed blaze.

and new bearing tree

A fir, 22" dia., bears S.61°W., 37.8 ft., mkd. T22S R5W S13 BT.

Corner is located in a four-strand barbed wire fence, 1.0 ft. South of a fence corner with fences extending N, E, S, and W. Each new bearing tree has a 2½" X ¼" magnetic nail (MAG-NAIL) driven at the base on the right side-center.

DCS0-GIS Corner visitation - 9/28/2005 - Typed: 1/19/2011 - C.S. File 67/33-1

Monument - 1¼" IP w/BC. Comment - OK

Fd. Ok by N. Hibbs, 8/2008 - M156-42